Remington Arms Co., Inc. Product Service Legal Case #:6890

Case Information

RE# Date Opened 249008 12/2/2011

Date Opened(PS) 11/22/2011

Date Closed 12/5/2011

Incident Date

Pre Lit Obsolete

Customer Information

Business

Last Name First Name

Street

City State Zip Age

Contact

Reporter Blackland Gun Works

Claims

Blackland Gun W 6900 Cty Rd 101 Taylor TX 76574

W 512-365-1306 E blacklandguns@eccwireless.com

Incident Information

Codes

Repair Est.

Medical Treatment

Medical Status

PΙ

PD

Cause: 4015 Improper Maintenance

Unknown

S Fired on bolt closing

Concern:1008 Fired on Bolt Closing

C

11/22/11 Per call from dealer, his customer brought a 700 in and said it fired when he closed the bolt.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Вы. DOM

Remington **Date Purchased**

CF/BA Where Purchased 700/270 WIN Accessories

n/a **Original Owner** B6205894 KA 5/7/1980

W TEXAS WHLSE ABILENE TX

TWO PIECE BASE

U

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash

Reim.

Settlement

Release Date

Reimbursement

Cash Settlement Date APV Date APV

Per Ilion, replace TPA, clean, test fire at BLSM program price

Repair/Replacement

Repair/Replacement

Cost 30.40

Release of Claims

12/12/2011

11/22/11 Emailing ARS.cm 12/12/11 Per Ilion, trigger assm very dirty and sticky. Trigger and sear work sluggish. Replace TPA, clean, test fire at BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/5/2011
Examination	Product Type		RF
	Action Type]	A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
	Description]	22" 270 WIN
	Date Code]	KA
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructe	d	_
	Muzzle/Crown	Slightly Worn;	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6890&Type=Case

12/12/2011

L	Condition	Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
1	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY.TRIG AND SEAR BINDING WILL FOLLOW DOWN
	Pull	Select	10+#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

6890

Dear Remington:

22" KAS/8"

One of my customers brought this Remington 700, serial number B6205894 to me to have you repair. The rifle will fire when you close the bolt and the safety is not working.

Thanks

Eric Winkelmann-owner
Blackland Gun Works
6900 CR 101
Taylor TX 76574
512-365-1306
blacklandguns@eccwireless.com

りませる B6205894 Model: 700



DEC 0 6 2011 DEC

Tit very Lipty + Sticky. Till9 + SIAR word stuggish. Replace TPA, Clear thest are under BCP for \$ 20.00 + ship

Quote

Service Request

Remington Service

Madison, NC 27025-0700



ATTN: Product Service #6890

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number

Serial Number / Description

SR00004609 B6205894

Model 700

BLACKLAND GUN WORKS 6900 COUNTY RD 101 TAYLOR, TX 76574 US

Email: blacklandguns@eccwireless.com

Date of Request:

11/22/2011

Date Printed: 11/22/2011

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our watranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Renson For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Fired on bolt closing

U.S. Department of Justice

Bureau of Alcohol, Tobacco, Firearms and Explosives

Federal Firearms License (18 U.S.C. Chapter 44)

In accordance with the provisions of Title I, Gun Control Act of 1968, and the regulations issued thereunder (27 CFR Part 478), you are licensed to engage in the business specified in this license, within the limitations of Chapter 44. Title 18, United States Code, and the regulations issued thereunder, until the expiration date

shown. See "WARNINGS" and "NOTICES" on reverse.

Direct ATF

ATF - Chief, FFLC

Correspondence To

244 Needy Road

Martinsburg, WV 25405-9431-

License Number

Chief. Pedefal Firearms Deersing Center (FFLC)

Expiration Date

July 1, 2012

Name

BLACKLAND GUN WORKS

Premises Address (Changes? Notify the FFLC at least 30 days before the move.),

6900 COUNTY RD 101 **TAYLOR, TX 76574**

Type of License

01-DEALER IN FIREARMS OTHER THAN DESTRUCTIVE DEVICES

Purchasing Certification Statement

The licensee named above shall use a copy of this license to assist a transferor of firearms to verify the identity and the licensed status of the licensee as provided by 27 CFR Part 478. The signature on each copy must be an original signature. A faxed, scanned or e-mailed copy of the license with a signature intended to be an original signature is acceptable. The signature must be that of the Federal Firearms Licensee (FFL) or a responsible person of the FFL. Leeftify that this is a true copy of a heense issued to the licensee named above to engage in the business specified of License."

Mailing Address (Changes?: Notity the FFLC of any changes i

WINKELMANN, ERIC WILLIAM BLACKLAND GUN WORKS 6900 COUNTY RD 101 FILE COPY TAYLOR, TX 76574-

nsee Responsible Person Sign Eric Winkelmann nsible Person Signature

Printed Name whateman effective 6500 county for 15175574 514.

ATF Form \$ (5340-11) Revised September 2008

November 22, 2011

Blackland Gun Works 6900 County Rd 101 Taylor, TX 76574

Subject: Case # 6890, Model 700, SR# 4609

Please include a copy of this letter with the firearm as well as the Service Request form. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the small ends of the box "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

Service Request

Remington Service

Madison, NC 27025-0700

ATTN: Product Service #6890

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN**.

Service Request Number Serial Number / Description Date of Request: 11/22/2011 SR00004609 B6205894 Printed: 11/22/2011 Model 700 Customer: Destination: BLACKLAND GUN WORKS Arms Services 6900 COUNTY RD 101 14 Hoefler Ave Ilion, NY 13357 US TAYLOR, TX 76574 US Email: blacklandguns@eccwireless.com Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Fired on bolt closing

Parts And Service Details

Material Type Description Qty Warranty Price Disc Amount

Needed

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

es Tax:

Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.) unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u> << <u>mailto:info@remington.com</u> >>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

Mailing Label:		
(cut here)		

Arms Services SR# SR00004609 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Product Service #6890



ARS LABEL REQUEST FORM

DATE:	11/22/2011	Service Request #	SR00004609	
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY: mitchellcs		email address:	Christy.Mitchell@remington.com	

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

BLACKLAND GUN WORKS 6900 COUNTY RD 101 TAYLOR, TX 76574 US SR00004609

Email: blacklandguns@eccwireless.com

RETURN ITEM TO:

ILN

Arms Services



Product Service #6890 ATTN;

4XX596 NOV 22, 2011 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969065584466 REF 1:SR00004609 REF 2: 1 OF 1

HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD RS 1.00 SD 0.00 DV 0.00 DC 0.00 0.00 COD DGD 0.00 AH 0.00 0.00 SP 0.00 TOT PUB CHG 12.03 PUB+HANDL ING 12.03







