

Remington Arms Co., Inc.
Product Service
Legal Case #:6872

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
247417	11/18/2011	11/21/2011	11/21/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		James	Burkett						H 850-871-6429 E jlb1111@bellsouth.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired when bolt was locked down	Concern:1008 Fired on Bolt Closing		Unknown
C				

12/8/11 Per note with rifle, it discharged when bolt was locked down.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	25791	B6589735	PF	6/1/1985
Date Purchased	Where Purchased	Accessories	Original Owner			
	DIXIE SHOOTERS SUP BLAKELY GA	BOTTOM HALF SEE THRU MOUNTS	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

12/8/11 Per Ilion, could not duplicate concern. Trigger assm dirty, rusty and set screws altered. Replace TPA, clean, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/21/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22: 270 WIN
	Date Code		PF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	METAL RUSTY,PITTED
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.017
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	---Select---	7#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		BOTTOM HALF SEE THRU MOUNTS

22"
PFL/YS
7#
017

JB

11/15/11

Enclosed is rifle I
called about. Rifle
discharged when bolt ¹⁰⁸⁷²
was locked down. I

spoke to someone in
repair and they said
to send here.

My phone # 850-871-6429,
Email address j161111@bellsouth.net

Thanks,
J L Burkett

JAMES BURKETT
(850) 871-6429
THE UPS STORE #0827
380 S TYNDALL PKWY
PANAMA CITY FL 32404-6724

10 LBS 1 OF 1
SHIP WT: 10 LBS
DATE: 15 NOV 2011

SHIP SRN SR00003710
TO: ARMS SERVICES
14 HOEFLER AVE

JB

could not duplicate concern.

T.A. dirty, rusty + set screws
Altered. replace TPA, clean +
test fire at 1/2 normal cost.

Quote

B6589735

Model: 700



RE00247417

RECEIVED
NOV 29 2011

BY:







