

Remington Arms Co., Inc.
Product Service
Legal Case #:6782

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
245351	11/1/2011	11/2/2011	11/2/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Burt	Cook	130 Cutstore Ct	Fayetteville	GA	30215		H 770-365-1099

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired on bolt closing Concern:1008 Fired on Bolt Closing			
C				

11/16/11 Per note with rifle, the hammer will drop (not always) when he cycles the bolt to the down position. Rifle used very little since 1980.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6527028	AW	3/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	J S OHSMAN HOUSTON TEXAS	TWO PIECE BASE	N			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	42.40	11/16/2011				

11/16/11 Per Ilion, trigger assm dirty and sticky, parts work sluggish. Replace TPA, clean, test fire at BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/2/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		AW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY PARTS WORK SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	8.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE



FACTORY REPAIR INSTRUCTIONS

(NOTE: Please print and complete this form, and then include it with your firearm.)

MODEL NUMBER: 700 BDL

SERIAL NUMBER: 659 6527028

Are you the original owner?:



YES



NO

Name:

Burt Cook

Date of Purchase:

1976, Oct or Nov?

Address (no PO Boxes):

130 Cutstone CT

City:

Fayetteville

State:

GA

Zip:

30215

Phone (Daytime): 770 365 1099

Fax:

Please describe your problem:

The hammer will drop (not always) when I cycle the bolt to the down position. This resulted in one accidental firing, although no one was injured.

* This gun has been used very little since 1980 - less than 50 rounds

Ammunition Information:

Manufacturer:

Type:

Other (i.e. bullet weight/type, shot size, powder):

Handload Information:

Powder Used:

Powder Weight:

Case/Hull Used:

Primer Used:

Bullet Type/Shot Size:

Reloader Used:

RECEIVED
NOV - 8 2011

BY:

22"
AWS/72
8.5"
1006

Brand of cleaning solution used:	Hops #9
How often do you clean the bore? (Months or Number of rounds)	after firing
How often do you clean the action? (Months or Number of rounds)	after firing
How often do you clean the trigger assembly? (Months or Number of rounds)	once a year if gun is being used
Brand of lubricant used:	Rem oil
How often do you lubricate the bore? (Months or Number of rounds)	after cleaning
How often do you lubricate the action? (Months or Number of rounds)	after cleaning
How often do you lubricate the trigger assembly? (Months or Number of rounds)	after cleaning
Ship your INSURED firearm by either UPS or Parcel Post to: H&R Firearms Attn: Arms Service Repairs 14 Hoefler Avenue Ilion, NY 13357	

IN YOUR FIREARM OR IN THE SAME BOX WITH THE
IF YOU FEEL YOU MUST SEND SPENT SHELLS
AND INCLUDE NAME, ADDRESS (WITH ZIP CODE),
FOR YOUR FIREARM.

ding it.
amage in shipping and handling. Preferably,
be returned.)
loss or damage.
ide the box. Shipments without a proper

Post. Remington is not responsible for
purchase insurance from your carrier.

Guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

T.A. dirty + sticky parts work
sluggish. Repha TPA clean + test
Rem under BLP for \$20.00 + ship

Serial
Number

6527028

Model: 700



RE00245351







