Remington Arms Co., Inc. **Product Service** Legal Case #:6786

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

11/22/2011 11/2/2011 11/23/2011 247695

Costello

Customer Information

Type **Business** First Name Last Name Street City State Zip Age Contact 7493 Heinrich Rd.

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

Incident

PD Cause: 4038 Could Not Duplicate Concern

Unknown

14075

Concern: 1020 Fired on Bolt Opening S

Terrance

C FBO

11/2/11: Customer called in. He had FBO w/rifle. He stated it happened back in 2009. He stated he read about some issues w/Model 700 on the internet & now he's concerned. df

Firearm Information

Mfg.

Type CF/BA

Model/Ga. 700/3006 SPRG **SKU** n/a

Serial Bbl. DOM A6697517 LV 2/1/1979

C 716-536-2424

Remington **Date Purchased**

Where Purchased

Accessories

Hamburg

Original Owner

BASCHE SAGE HDW BAKER OREGON TWO PIECE BASE

Υ

CONCERN:FBO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim.

Cash

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Date

APV

Date **APV**

Per Ilion - Quote to repair under BLM

Repair/Replacement

Repair/Replacement

Cost

Date

\$30.40

12/9/2011

11/2/11: Mailing ARS & forms. df 11/3/11: Customer called w/correct serial #. df 12/9/11: Per Ilion - Could not duplicate concern. TA very dirty. Replace TA, clean & test fire under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/23/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6786&Type=Case

12/9/2011

	Description		22" 3006 SPRG
	Date Code		LV
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	}
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False]
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	<u> </u>
	Condition	Slightly Worn; Functioning	VERY DIRTY
Trigger	Pull	Select	6#
1118801	Altered	False	<u> </u>
	Sub-Assembly	M/700 Bolt Lock]
Non-Remington Components	Description		TWO PIECE BASE



6786

November 3, 2011

Terrance Costello 7493 Heinrich Rd. Hamburg, NY 14075 Phone: 716-536-2424

Ref: #6786, Model 700, Serial # A6697517

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686


Fax: 336-548-7872

enclosure

Model: 700 RE00247695 could not dup haste concerns
T.A. very dinty. My how TOA,
cle AN + TOST Rine under 34P
Lon & Zo. 00 + 5hp

Quote

Remington Arms Company, LLC ● 870 Remington Drive ● P.O. Box 700 ● Phone 800-243-9700 ● www.remington.com



BY:

Service Request

Remington Service

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number | Serial Number | Description 11/02/2011 Date of Request: SR00002728 A6697517 Printed: 11/03/2011 Model 700 Center Fire Destination: Customer: TERRANCE COSTELLO Arms Services 7493 HEINRICH RD. 14 Hoefler Ave HAMBURG, NY 14075 US Ilion, NY 13357 US Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Product Service # 6786 - FBO Parts And Service Details

Material Type Description Qty Warranty Price Disc Amount
Needed

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: .00
Est Sales Tax: .00

ARS LABEL REQUEST FORM

DATE: 11/03/2011	Service Request #	SR00002728
QUANTITY:	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY fulcherdm	email address:	I WILL MAIL LABEL

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

TERRANCE COSTELLO 7493 HEINRICH RD. HAMBURG, NY 14075 US SR00002728

Email:

RETURN ITEM TO:

ILN

Arms Services



4XX596 SVC GNDCOM NOV 3, 2011 ALL CURR USD ACT UT 10.0 LBS 1 OF 1 TRACKING# 1Z4XX5969065449148

REF 1:SR00002728

REF 2:CD

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: DV 0.00 DC 0.00 SVC T/P USD COD 0.00 COD DGD RS 0.50 SD 0.00 0.00 AH 0.00 PR TOT PUB CHG 8.15 SP 0.00 PUB+HANDLING 8.15

ATTN: Product Service



