

Remington Arms Co., Inc.
Product Service
Legal Case #:6689

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
243524	10/14/2011	10/17/2011	10/17/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Dave & Rex's Outdoor World		Dave & Rex's Ou	825 W. Cumberland Gap Pkwy	Corbin	KY	40701		W 606-523-2277

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S Fires on bolt closing	Concern:1008 Fired on Bolt Closing			
C				

10/26/11 Per note with rifle, gun goes off when bolt is locked down. Gun shot 12 times, went off 3 times, killed 9 deer.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	20000	6634136	AX	3/1/1973
Date Purchased	Where Purchased	Accessories	Original Owner			
	CULLUM&BOREN DALLAS TEXAS		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean and test fire under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	45.40	10/26/2011				

10/26/11 Per Ilion, trigger assm has a partially dried and sticky lube residue causing the parts to work sluggish. Replace TPA, clean and test fire under BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/17/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		AX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	STICKY LUBE RESIDUE WILL FOLLOW DOWN
	Pull	---Select---	9.75#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

6689 149094

Remington

22"
AK 3/73
9.75#
.008

CUSTOMER'S ORDER NO.		DEPARTMENT		DATE	
				10-11-11	
NAME Dave & Rex's Outdoor World					
ADDRESS 825 W. Cumberland Gap Parkway					
CITY, STATE, ZIP Corbin, Ky. 40701 / 606-523-2277					
SOLD BY	CASH	C.O.D.	CHARGE	ON. ACCT.	PAID OUT

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1			
2	Rem 700 ADL Deluxe		
3	Serial# 6634136		
4			
5			
6	Gun goes off when bolt		
7	is locked down		
8			
9	Gun shot 12 times		
10	went off 3 times		
11	Killed 9 Deer		
12			
13			

6634136
Model: 700



RE00243524

RECEIVED
OCT 19 2011

BY:

T.A. has a partially dried + sticky
LUBE residue causing the parts
to work sluggish. Replaced TPA, clean
+ rest fire under BLP for \$20.00
ship

Q note





