

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6727

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
244427	10/24/2011	10/25/2011	10/25/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Terrence	Flaughter	432 Wengler Ave	Sharon	PA	16146		

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when he moved the safety	Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release	Unknown	
C				

10/26/11 Per note with rifle, last day of deer season Dec 2009 he was coming out of the woods and went to unload his rifle, he dropped the floorplate and put 3 shells in his pocket. He went to extract the last shell and when he touched the safety the gun went off by itself. He has hunted with this gun for 30 years and never experienced anything like this. He has seen all the hype on tv after the fact.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6880929	AA	3/7/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	JC PENNY CO STATESVILLE NC	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	42.40	10/26/2011				

10/26/11 Per Ilion, could not duplicate concern. Trigger assm dirty and sticky, parts work sluggish. Replace TPA, clean and test fire at BLSM program price of \$20 - shipping.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		10/25/2011

Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		AA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY PARTS WORK SLUGGISH
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

TERRENCE FLAUGHER  
432 WENGLER AVE  
SHARON PA 16146  
SHIP TO:  
10 LBS  
RS

6727

22"  
AA3/80  
6#  
1007

public documents

To Whom It May Concern;  
Wednesday,

October 19, 2011

I Called Remington Arms earlier this month, and talked to someone in customer service about this matter of my riffle. I was told to enclose this information with my riffle. Last day deer season December of 2009, I was coming out of the woods, and went to unload my riffle, I dropped the floorplate, put 3 shells into my pocket. I went to extract the last shell and when I touched the safety, the gun went off by itself. My best friend was standing about 6 feet to my left and scared both of us, like you wouldn't believe. I hunted with this gun for 30 years, or better and never experienced anything like this. I have seen all the hype on television after the fact. I hope that you can figure this out and fix this problem. I would like to pass this riffle on to my grandson, as I am almost ready to retire from the sport of hunting.. I just wanted to thank you for listening to me.

address is;  
432 Wengler Ave.

Sincerly Yours;

Terrence Flaugher

my  
could not duplicate concern.  
T-A. dirty + sticky parts work  
SLU 99ish. replace TPA, clean  
+ test fire under BLP for  
B 20.00 + ship

Quote

Sharon, Pa 16146

Terrence L. Flaugher

RECEIVED  
OCT 26 2011

124-346-

9821

Serial  
Number:

A6880929

BY:

Page

Model: 700



RE00244427







