

Remington Arms Co., Inc.
Product Service
Legal Case #:6354

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
235383	7/11/2011	7/18/2011	7/18/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Martin	Forte Jr.	407 Sunlit Terrace	Utica	NY	13502		H 315-733-2807

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C Rifle fired unexpectedly				

Customer brought rifle to Ilion factory. He stated that rifle fired unexpectedly & wants the TA replaced with a XMP trigger. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6373857 ET	10/1/1970
Date Purchased	Where Purchased	Accessories	Original Owner		
	HORROCKS IBBOTSON UTICA NY	SCOPE,RINGS,TWO PIECE BASE,SLING	U		

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Rembursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair under BLM			Remington/700/CF/BA			
	Repair/Replacement Cost	Repair/Replacement Date				
	\$32.40	7/26/2011				

7/26/11: Per Ilion - Could not duplicate concern. TA very dirty & sticky. Replace TA, clean & test fire under BLM. Repair was completed & shipped COD. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/18/2011
	Product Type		RF
	Action Type		A

	Assigned To	T.NAGLE	
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		ET
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	ACTION DIRTY,RUSTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	---Select---	8#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE,SLING

Receipt Of Firearm(s) Delivered to the Plant for Repair

Firearm Checked For Live Ammunition ☒

Driver's License ID# 638-551-175

Delivery Date 7/8/11

Customer Name (Print) MARTIN P. FORTE, JR Employee (Y) ☒

Address 407 SUNLIT TERRACE City UTICA

State NY Zip 13502 Phone Number (315) 733-2807

Manufacturer Remington

Firearm Description Model 700 Cal./Ga. 30.06

Serial Number 6373857

Stock/ Fore-end Condition - circle the description

(Excellent, Good, Fair, Poor, Fancy, Plain, Synthetic, Wood)

Comments on Stock/ Fore-end condition _____

Metal Condition - circle the description

(Excellent, Good, Fair, Poor, Fancy, Plain Stainless Steel)

Comments on Metal condition _____

Barrel Type (VT. Rib; Plain; Deer; Stainless Steel) Barrel length _____

List additional accessories: IE (Scope) Sling, Gun case and description;

Customer request: RIFLE FIRED UNEXPECTEDLY, REPLACE TRIGGER WITH XMP TRIGGER ASMBLY - SPOKE TO BRUCE TRAVIS

Return Process Return to Clark St. Ent. ☒ Return via UPS []

By signing this receipt the person delivering the firearm understands to be the only person to receive the firearm upon completion of repairs.

Signature [Signature] Date 7/8/11 could not duplicate concern T.A. very dirty + sticky replace TPA, clean + test fire under BCP for \$20.00.

Signature [Signature] Date 7/8/11 person delivering firearm

Signature [Signature] Date 7/11/11 security officer

Arms Service / CSR

RECEIVED JUL 20 2011

Customer Pick Up Verification

red the above described firearm to the lawfully possess a firearm in New York State.

_____ Date ____/____/____ same who delivered

_____ Date ____/____/____ turning the firearm

Serial Number: 6373857

Model: 700



RE00235383

Remington.







