

Remington Arms Co., Inc.
Product Service
Legal Case #:6419

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
236796	7/29/2011	8/3/2011	8/3/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mtn.	---	Gander Mtn.	19302 Interstate 45	Spring	TX	77373		W n/a

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Gun has gone off without being fired			

Dealer sent gun in for consumer. Consumer stated that gun went off without being fired. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6618985	AX	3/1/1973
Date Purchased	Where Purchased	Accessories	Original Owner			
	PEDEN IND INC HOUSTON TEXAS		U			

CONCERN: WENT OFF WITHOUT BEING FIRED

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	8/8/2011				

8/8/11: Per Ilion - Could not duplicate concern. TA set screws altered. Replace TA, clean & test fire under BLM - quote. Dealer apprvd quote & charged to open account number. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		8/3/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		AX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Worn; Functioning	SCRATCHES,MARS,DENTS
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.004
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	



6419

Service Request

Service Order # 4499

22"
A& 3/73
3.5"
.004

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00727
14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 07/20/2011

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 5-76-201-01-8B-01220
Attn: Gun Parts Dept.
19302 Interstate 45
Spring, TX 77373

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.
Model: 700

Type: Rifle
Cal/Ga.: .30-06cal

Serial Number: 6618985
Cased?: ☐

DESCRIPTION OF ITEM RETURNED:

Remington 700

REASON FOR RETURN:

Customer would like the new trigger in his gun. Recall trigger system, complains gun has gun off without gun being fired...

ATTENTION VENDOR

Please contact me with any questions or concerns.

Dan Golden

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to: **Gander Mountain**
Attn: Cindy Kilbride
180 East Fifth Street
St. Paul, MN 55101

RECEIVED
AUG 04 2011

BY:.....

could not duplicate concern.
T.A. set screws altered.
replace TPA, clean + test fire
under BLP for \$ 20.00 + \$ ship

Number:

6618985

Model: 700



RE00236796







