

Remington Arms Co., Inc.
Product Service
Legal Case #:6361

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
235446	7/12/2011	7/18/2011	8/5/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		David C.	Hinton	519 Paradise Rd.	Greenville	KY	42345		H 270-338-5798 C 270-543-3843 E davidchinton@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Shot out rear window of a Suburban	Cause:4038 Could Not Duplicate Concern		Unknown
S	Concern:1007 Fired on Safe Release			
C	FSR			

Customer shipped gun to us with our repair form filled out. He stated the gun had a FSR inside a Suburban in November 2010. Shot out the rear window. His 16 yr old grandson had been hunting with the gun & the boy's father was checking to see if the gun was unloaded & when he took the gun off safe & touched the bolt - it discharged. Customer would like the bolt lock modification done. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	6703652	BY	1/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
	BOETTICHR KELOG EVANSVIL IN	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair @ n/c - goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$62.40	8/5/2011				

7/26/11: Per Ilion - Could not duplicate concern. We will replace TA, clean & test fire under BLM at n/c - goodwill gesture. I will close case after I get parts list. df 8/5/11: Got parts list. File closed. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/18/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 22-250 REM
	Date Code		BY
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS,SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	6.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Cell Phone # 270-543-3845

6361

X

24"
BY 1/7
6.5#
1008

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 BDL		Serial Number: 670 3652	
Are you the original owner? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: DAVID C. Hinton		Date of Purchase: 1985	
Address (no PO Boxes): 519 PARADISE RD. Greenville, Ky. 42345			
City: Greenville, Ky.	State: Ky	Zip: 42345	
Phone (Daytime): 270-338-5198		Fax:	
E-mail Address: DAVIDCHINTON@GMAIL.COM			
<input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem: This gun discharged inside a SUBURBAN WAGON during deer season in November-2010. My son age 52, who has hunted all his life owns 2 Remington 742 30-06 Automatics. His 16 year old son was hunting with this gun. After driving from woods to home, my son decided to double check all guns, to make sure they were all unloaded. He picked up this gun and tried to work the bolt: he had to move the safety to the Firing Position, and			
Ammunition Information: When he touched the bolt, it discharged, shooting out			
Manufacturer: Remington		Type: 22-250	
Other (i.e. bullet weight/type, shot size, powder): 55 grain ATD Soft Point			
Handload Information:			
Powder Used:	Powder Weight:		
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:		
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: Outers			
How often do you clean the bore? (Months or Number of rounds) After each outing or hunting trip.			
How often do you clean the action? (Months or Number of rounds)			
How often do you clean the trigger assembly? (Months or Number of rounds) Only the outside of gun			
Brand of lubricant used: Outers			

Remington
22-250
55 grain
2 22501

There were
2 of his
children in
vehical at
this time

OVER
ON
BACK

RECEIVED
JUL 20 2011

BY:







