

Remington Arms Co., Inc.
Product Service
Legal Case #:6581

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
240864	9/16/2011	9/19/2011	9/19/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Paul	Hutto	23654 US Hwy 231	Troy	AL	36081		H 334-670-9909 C 334-566-9492 F 334-566-4422 E LynnHutto56@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fires on safety release	Concern:1007 Fired on Safe Release		
C				

9/27/11 Per letter with rifle, if a round is in the chamber and the safety is flipped forward, the gun is subject to fire.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	B6273167	PB	6/2/1981
Date Purchased	Where Purchased	Accessories	Original Owner			
	BECK GREGG IND ATLANTA GA	SCOPE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	55.62	9/27/2011				

9/27/11 Per Ilion, could not duplicate concern. Trigger assm dirty and rusty. Replace TPA, clean, test fire under BLSM program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/19/2011
	Product Type		RF
	Action Type		A

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6581&Type=Case>

9/27/2011

	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		PB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	---Select---	6.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

SEPT. 6
~~June 10~~, 2011

6581

22"
PB6/81
6.5#
1009

Remington Arms Co

Attn: Arms Service Div / Repairs

14 Hoefler Ave

Ilion, NY 13357

Re: Remington Model 700 / 270 caliber / Left hand SER# B6273167

Dear Sir,

I am returning the above referenced ^{RIFLE} Shotgun in hopes of having it repaired. The problem with the gun is, if a round is in the chamber and the safety is flipped forward, the gun is subject to fire.

If there is a charge for the repair or if further information is needed, please call me at 334-670-9909 or 334-566-9492.

Thank you

Paul Hutto

23654 U S Hwy 231

Troy, AL 36081

Email: LynnHutto56@yahoo.com

Fax 334-566-4422

RECEIVED
SEP 23 2011

BY:.....

Serial Number:

B6273167

Model: 700



RE00240864

could not duplicate concern.
T.A. dirty + rusty. Replace TAA,
clean + test fire under BCP
for \$ 20.00 + Test

Quote







