Remington Arms Co., Inc. Product Service Legal Case #:6970

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 12/2/2011

12/21/2011 251417

12/22/2011 11/19/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

W 518-767-2018

Incident

Brian Keris

1908 Bentley Rd Schenectady NY 12309

F 518-767-2106 E bak5081@hotmail.com

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ PD

Cause: 4038 Could Not Duplicate Concern

S Concern: 1007 Fired on Safe Release Unknown

C FSR

12/2/11: Customer called in. He stated on 11/20/10 he had FSR. No damage, No injury. He said on 11/19/11 he had FSR. No damage, No injury. df

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CONCERN: FSR

CF/BA

700/3006 SPRG

27289

G6598268 OA 7/17/2006 6:15:30 PM

Date Purchased Where Purchased

Accessories Original Owner

DICK S SPORTING GOODS

Y

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims **Release Date**

Reimbursement

Cash

Reim.

Settlement Date APV

Cash Date APV

Per Ilion - Quote to repair

Repair/Replacement

Repair/Replacement

Cost

Date

12/2/11: Mailing ARS & forms. Box order# 1278245. df 1/4/12: Per Ilion - Could not duplicate concern. TA dirty. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner	_	B.TRAVIS
	Exam Date	. *	12/22/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6970&Type=Case

1/16/2012

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		OA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	- N. J L.
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift ·	Select	.012
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
Trigger	Pull	Select	4#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Remington

2211 0A7/06 4# 1012

691

December 2, 2011

Brian Keris 1908 Bentley Rd Schenectady, NY 12309 Phone: 518-767-2018

Ref: #6970, Model 700

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

Model: 700

Could not Stip truste concern T. A. dirty. CAN Often to replace TPA clean + Test Rune at the Normal cost

Quote

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description

SR00005557

Model 700 Center Fire Caliber: 3006

Customer:

BRIAN KERIS 1908 BENTLEY RD

SCHENECTADY, NY 12309 US

Date of Request:

12/02/2011

Date Printed: 12/02/2011

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 6970 - FSR

Parts And Service Details

Material

Type

Description

Qty Needed Warranty

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00 .00

Print

Reset

Model	Serial
Number: megec 700	Number: 66 598268
Are you the original ow	
Name: Brown A KREES	Date of Purchase:
Address (no	PO Boxes):
City: 1908 (JENTUCY ROAD	0C N Y
(5は) Phone (Daytime): フレリーチのほこつ	Fax: (5)8) 769 - 2106
E-mail Address:(if e-mail address is provid	
be sent) BAK 5081 @ Htc	TAME, COM
E-mail A	
☐ I would like to receive future €	
Please describe your proble	THIS FIFTE HAS FIRED
W/O PALLING THE TRACE	er panter sust
majore THE SAFETY F	
•	
:	
500 cha	racters left
Ammunition I	nformation:
Manufacturer: 2 Evin ING TEN	Type: 30-06 150 Cm. 6 Bodes
Other (i.e. bullet wei powder):	
Handload In	formation:
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleani	ng and Lubrication):

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds) HWE SHOT LESS THE HORALITY					
How often do you clean the trigger assembly? (Months or Number of rounds)					
Brand of lubricant used: 井ついりに、					
How often do you lubricate the bore? (Months or Number of rounds)					
How often do you lubricate the action? (Months or Number of rounds)					
How often do you lubricate the trigger assembly? (Months or Number of rounds)					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >☑ YES ☐ NO					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) പ്രചരിച്ച കുറി					
What were the services performed?) The Pin Assenbly mark Function					
Ship your INSURED firearm by either UPS or Parcel Post to:					
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
■ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.					
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper					

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

DATE:	12/02/2011	Service Request #	SR00005557
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL

Business:

4 . . .

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

BRIAN KERIS 1908 BENTLEY RD SCHENECTADY, NY 12309 US

SR00005557

Email:

RETURN ITEM TO:

ILN

Arms Services





4XX596 DEC 2, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS TRACKING# 124XX5969066369974 REF 1:SR00005557 REF 2:

HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC 0.50 DV 0.00 RS 0.50 DC 0.00 DGD 0.00 SD 0.00 BD 0.00 SD 0.00 DGD 0.00 SP 0.00 TOT PUB CHG 7.94 PUB+HANDLING 7.94





