

Remington Arms Co., Inc.
Product Service
Legal Case #:7177

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
250864	12/17/2011	12/30/2011	1/3/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Roger	Kubis	W1700 Heineman Ln.	Cochrane	WI	54622		H 608-797-3962

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

Customer sent gun in w/note. He stated gun had a FBC. No reported injury or damage. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/2506 REM	25789	E6292172	PQ	6/27/1996
Date Purchased	Where Purchased	Accessories	Original Owner			
	SIMMONS GUN SPECIALTIES INC		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						
	Repair/Replacement Cost	Repair/Replacement Date				

1/4/12: Per Ilion - Could not duplicate concern. Offer to replace TA, clean & test fire @ 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 2506 REM
	Date Code		PQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	

J. # SR 5750

This rifle fired when I closed the bolt,
Only happened once.

I ordered from you the screws in the
sight holes, are they the proper ones?

target from this rifle

7177

24"
PQ6/96
6#
1011

Roger Kulis

W1700 Weinman Ln.

Cochrane, Wi. 54622

608-797-3962

E6292172

Model: 700



RE00250864

could not duplicate concern
was often to replace TPA, clean
+ rest fire at 1/2 normal cost.

Quake

RECEIVED
JAN - 4 2012

BY:







