

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6439

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 237555 | 8/9/2011    | 8/10/2011       | 8/10/2011   |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street      | City        | State | Zip   | Age | Contact                          |
|----------|----------|------------|-----------|-------------|-------------|-------|-------|-----|----------------------------------|
| Incident |          | Joe        | Lawson    | 568 FM 2694 | Shelbyville | TX    | 75973 |     | H 936-598-2154<br>C 936-572-0402 |

## Incident Information

| Claims | Codes                            | Repair Est.                        | Medical Treatment | Medical Status |
|--------|----------------------------------|------------------------------------|-------------------|----------------|
| PI     |                                  |                                    |                   |                |
| PD     | Cause:4038                       | Could Not Duplicate Concern        |                   |                |
| S      | Fires when safety is put on fire | Concern:1007 Fired on Safe Release |                   | Unknown        |
| C      |                                  |                                    |                   |                |

8/18/11 Per note with rifle, the trigger on this gun fires when safety is put on fire.cm

## Firearm Information

| Mfg.           | Type                          | Model/Ga.    | SKU            | Serial   | Bbl. | DOM      |
|----------------|-------------------------------|--------------|----------------|----------|------|----------|
| Remington      | CF/BA                         | 700/6 MM REM | n/a            | B6355688 | LC   | 2/5/1982 |
| Date Purchased | Where Purchased               | Accessories  | Original Owner |          |      |          |
|                | SPORT SOUTH INC SHREVEPORT LA |              | U              |          |      |          |

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement                                                           | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|----------------------------------------------------------------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| Per Ilion, replace TPA, clean and test fire under BLSM program price |                   |              |               |                 |                |               |

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| 50.88                   | 8/18/2011               |

8/18/11 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean and test fire under BLSM program price of \$20 + shipping.cm

*8/18 He has mailed approval and check.*

## Examination[Remington/CF/BA]

| Part        | Sub-Part               | Code                        | Comment     |
|-------------|------------------------|-----------------------------|-------------|
| Examination | Examiner               |                             | B.TRAVIS    |
|             | Exam Date              |                             | 8/10/2011   |
|             | Product Type           |                             | RF          |
|             | Action Type            |                             | A           |
|             | Assigned To            |                             | T.NAGLE     |
| Cause       | 4038                   | Could Not Duplicate Concern |             |
| Barrel      | Description            |                             | 22" 6MM REM |
|             | Date Code              |                             | LC          |
|             | Bore Plugged           | False                       |             |
|             | Bulged                 | False                       |             |
|             | Fired                  | False                       |             |
|             | Fired while Obstructed |                             |             |

|              |                        |                            |                        |
|--------------|------------------------|----------------------------|------------------------|
|              | Muzzle/Crown Condition | Slightly Worn; Functioning |                        |
| Bolt         | Firing Pin             | Slightly Worn; Functioning |                        |
|              | Shroud                 | Slightly Worn; Functioning |                        |
|              | Face                   | Slightly Worn; Functioning |                        |
|              | Handle                 | Slightly Worn; Functioning |                        |
|              | Stop                   | Slightly Worn; Functioning |                        |
| Extractor    | Condition              | Slightly Worn; Functioning |                        |
|              | Cut Condition          | Slightly Worn; Functioning |                        |
|              | Ext/Eject Test         | False                      |                        |
| Locking      | Block Condition        | ---Select---               |                        |
|              | Lug Condition          | Slightly Worn; Functioning |                        |
|              | Notch Condition        | ---Select---               |                        |
| Overall      | Exterior Condition     | Worn; Functioning          |                        |
|              | Stock Condition        | Worn; Functioning          |                        |
|              | Fore End Condition     | ---Select---               |                        |
| Receiver     | Condition              | Slightly Worn; Functioning |                        |
|              | Bulged                 | False                      |                        |
| Safety       | Description            |                            | M/700 BOLT LOCK SAFETY |
|              | Function               | Like new; Functioning      |                        |
|              | Sub-Assembly           | Non-ISS                    |                        |
| Sear         | Lift                   | ---Select---               | .010                   |
|              | Notch                  | Slightly Worn; Functioning |                        |
|              | Tests                  | Test Fired                 | False                  |
| Feeding Test |                        | False                      |                        |
| Trigger      | Condition              | Slightly Worn; Functioning | DIRTY                  |
|              | Pull                   | ---Select---               | 3.5#                   |
|              | Altered                | True                       | SET SCREWS ALTERED     |
|              | Sub-Assembly           | M/700 Bolt Lock            |                        |

# Safety Modification Program

22"  
LC28  
3.5  
1010

6439

Joe LAWSON  
568 FM 2694  
Shelbyville TEXAS 75973

Serial no. B6355688  
Mod 700 6mm

The trigger on this gun fires when safety is put on fire. IT IS UNSAFE. Please replace trigger with an adjustable trigger.

PLEASE CALL ME ABOUT THE CHARGES OR QUESTIONS.

HOME PHONE 936-598-2154  
CELL 936-572-0402

B6355688

Model: 700



RE00237555

could not duplicate concern  
T.A. dirty + set screws altered  
uplace TPA clean + test R in  
under BLP for \$ 20.00 + ship

Quote

RECEIVED

BY: .....

125.88  
27. —  
35. —  
87.88  
37. —  
50.88











