

Remington Arms Co., Inc.
Product Service
Legal Case #:6335

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
234993	7/6/2011	7/7/2011	7/7/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Tony	Lee	106 Morris St.	Florence	KY	41042		C 859-609-2444

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1028 Fired With Safe ON			
C FSR				

Customer sent firearm in. He stated it fired while the safety was engaged. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	25775	C6581374	WK	8/3/1990
Date Purchased	Where Purchased	Accessories	Original Owner			
	ARKANSAS IMPORT & DISTRIB. CO.	SCOPE BASE	U			

CONCERN: FIRED W/SAFE ON

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV

Per Ilion - Quote
to repair

Repair/Replacement Cost	Repair/Replacement Date

7/21/11: Per Ilion - Could not duplicate concern. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. df
7/21/11: I called customer concerning quote & he doesn't want to pay the quote to have the trigger replaced. He stated to Return as Received if we did not find anything wrong. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/7/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		22" 308 WIN

Barrel	Date Code		WK
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

To Whom it may Concern,

6335

22"
W/K 8/9
4.5"
D11

I WAS instructed to return my
Remington 308^{win} Model 700 rifle because
it Fired while the safety was engaged.
Also, could you please remove the scope
base.

Sincerely yours,
Tony Lee

Cell # 859-609-2444

Home Add,

106 MORRIS ST.

FLORENCE KY

41042

RECEIVED
JUL 20 2011

BY:.....

Serial Number:
C6581374

Model: 700



RE00234993

could not duplicate concern
can offer to replace TPA,
clean + Test fire AT 1/2
non mal cost.

Quote





