

Remington Arms Co., Inc.
Product Service
Legal Case #:6514

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
239263	8/29/2011	8/30/2011	8/30/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Fernando H	Lucero	1989 N El Dorado Ct	Chandler	AZ	85224		H 480-695-6813 E FHLUCERO@COX.NET

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fired when safety was released	Concern:1007 Fired on Safe Release		
C				

9/12/11 Per note with rifle, rifle discharged when he moved from safe to fire in order to unload it. The rifle was pointed in a safe direction.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	B6263013	DA	9/22/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	LORE CORP EL PASO TX	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	45.40	9/13/2011				

9/12/11 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean, test fire under BLSM program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/30/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		DA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

6514

2211
DA9/00
4#
008

Model Number: 700		Serial Number: B6263013	
Name: Fernando H. Lucero		Date of Purchase: 11/6/2006	
Address (no PO Boxes): 1989 N El Dorado Ct			
City: Chandler	State: AZ	Zip: 85224	
Phone (Daytime): 480-695-6813		Fax:	
E-mail Address: FHLUCERO@COX.NET			
Please describe your problem: Rifle discharged when I moved from S to F in order to unload it. Fortunately gun was pointed in a safe direction avoiding a serious accident.			
359 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<input type="checkbox"/> WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.			
Record the serial number of your firearm before sending it. <ul style="list-style-type: none"> prevent further damage in shipping and erably, ship in a al boxes may not be returned.) ur firearm to prevent loss or damage. her UPS or Parcel Post. Remington is not or damage or loss t to purchase insurance from your carrier. 			
<input type="button" value="Reset"/>			

Serial Number:

B6263013

Model: 700



RE00239263

could not duplicate concern
T.A. dirty + set screws altered
replace TPA, clean test line
under BCP Ron @ 20.00 + ship

Quote

RECEIVED
SEP 06 2011

BY: _____









