Remington Arms Co., Inc. Product Service Legal Case #:6357

Case Information

Date Opened Date Opened(PS) RE# **Date Closed Incident Date** Pre Lit Lit Obsolete 7/18/2011 235408 7/11/2011 7/18/2011

Customer Information

Business First Name Last Name Street Zip Age Contact Type City State W 989-697-5341 1212 N. Huron Rd. Frank's Great O Reporter Frank's Great Outdoors Linwood 48634 MI F 989-697-3862 H 989-846-6090 Patrick **McBride** Incident

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status

ΡI

PD Cause:4006 Altered Adjustments or Components

Concern:1025 Unexplained Discharge - No Mention of Safety Position S Unknown

Fires when bolt is C touched

Dealer sent rifle in for customer. Repair form stated that gun misfires & fires when bolt is touched. df

Firearm Information

Mfg. Model/Ga. **SKU** Bbl. DOM Type Serial Remington CF/BA 700/3006 SPRG n/a A6822813 DV 9/21/1979

Date Purchased Where Purchased Accessories **Original Owner**

BOBS GUNS & SUP WEVER IOWA TWO PIECE BASE U

CONCERN:MISFIRES

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Release Date Settlement Reimbursement Date Settlement Date APV APV

Per Ilion - Quote to repair under BLM

Repair/Replacement Cost Repair/Replacement Date

\$30.40

7/26/2011

7/26/11: Per Ilion - TA dirty & sticky & set screws altered. Replace TA, clean & test fire under BLM - quote. I spoke to Ray @ store. He had me fax the quote to him & he asked me to contact the customer. I called customer & left a msg for him to call me concerning quote for \$37. df 7/27/11: Mary McBride called & apprvd repair & paid by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		7/18/2011	
Examination	Product Type		RF	
1	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4006	Altered Adjustments or Components		
	Description		22" 3006 SPRG	
	Date Code		DV	
	Bore Plugged	False		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6357&Type=Case

7/27/2011

	Bulged	False	7
	Fired	False	7
Barrel	Fired while Obstructed		4
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	1
<u> </u>	Stop	Slightly Worn; Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	1
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description	· · · · · · · · · · · · · · · · · · ·	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY TRIGGER NOT RETURNING WILL FOLLOW DOWN
Trigger	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE



989-697-5341 Phone 989-697-3862 Fax 224 DV 9/7 224

RETURN MERCHANDISE FORM

Vendor:	14 Hoefle	r Ave	7-7-11	•		
Contact:	Flion NY 13 Repair	Reaso	on: Return Defecti	ve Merchan	dise	
Vendor RA	;	·				
Account #:	·	Credit	Sports Inc. #290	Credit Fra	ınk's Great Out	doors
Comments:	Gun Mis	Fires + Fire	es when 1	poltis	touche	71
Very		+ unreliabl			test Fi	<u>re</u>
Custon	_ / \ 11	K Mc Bride	A -	aniks	- Dark	
QTY	STYLE	DESCRIPTION		EACH	TOTAL	
1	700 BOL	A	30-06			\$0.00
	,	W/weaver bas				\$0.00
and the state of t						\$0.00
			*			\$0.00
482	2813					\$0.00
	2010					\$0.00
idel: /	~~ . ••••• •••• •••• •••• ••••		<u></u>			\$0.00
		<u> </u>		PECI	EIVED	\$0.00
			· · · · · · · · · · · · · · · · · · ·		0 2011	\$0.00
RE	002354	N8			-	\$0.00
				BY:	*********	\$0.00
·		J.A. DI	izty, strcki d. rup lace neunden ?	1 set	screws	\$0.00
		Alterze	d. rup lace	TPA, CO	EANL	\$0.00
		Test fi	nunder ?	SLD Ror	00.05	\$0.00
		+ Ship	0			\$0.00
i		**************************************	You P	•		\$0.00
			FREI	GHT		
		·	TOT	AL .		\$0.00

Quotation

REMINGTON ARMS SERVICE PO Box 700

ARMS SERVICE Estimating Report

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE. Repair Number Serial Number / Description Date Received: 07/11/2011 RE00235408 A6822813 Estimate Date: 07/19/2011 Model 700 Center Fire Caliber: 3006 SPRG Date Printed: 07/26/2011 Customer: Return To: FRANK'S GREAT OUTDOORS FRANK'S GREAT OUTDOORS 1212 N HURON RD 1212 N HURON RD LINWOOD, MI 48634 US LINWOOD, MI 48634 US Please Circle One: VISA MC DISCOVER Card No. Open Account: R______PO Number:_____ Approval Signature:) Time to Call: Daytime Phone: (____ If you desire any change, please use the reverse side for your comments and mark this box. Reported Found Found Found Found Forward to PRODUCT SERVICE FOR INSPECTION M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Technician Comments ... trigger assm dirty, sticky and set screws altered. replace trigger plate assm, clean and test fire under bolt lock program for \$20.00 + shipping ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.) Material Description Otv Warranty Otv Price Disc Amount Type Needed From Inv X-MARK PRO 700 TRIG ASSB RH BLACK (OS) 1 1 F305570B Part Warranty .00 0 .00 17.00 0 1 1 4000114 Service GR-SHIPPING & HANDLING (GUN REPAIR) Billable 17.00 20 1.00 0 20 4000116 Service GR-LABOR Billable 20.00 4000119 Service **GR-TEST** 1 Warranty 1 .00 0 .00 Sub Total: 37.00 Est Sales Tax: .00

\$37.00

Grand Total:

Remington.

FACSIMILE TRANSMITTAL SHEET

To:	Ray	Date:	July 26, 2011	
Company:	Frank's Great Outdoors	From:	Dell Fulcher	
Fax No.:	989-697-3862	Fax No.:	336-548-7872	
Phone No.:	989-697-5341	Phone No.:	1-800-243-9700	
Number of p	ages including Cover Sheet:	2	Press 0 and ask for ext 8686	
COMMENTS:				
Quote to repair				
<u></u>				

PRIVILEGED AND CONFIDENTIAL

This facsimile is intended only for the use of the individual or entity to which it is addressed and may contain information that is privileged, confidential and exempt from disclosure. If you are not the intended recipient please do not disseminate, distribute, or copy this communication. Instead, please notify the sender immediately by return fax or by telephoning the number above and discard all copies of this fax.

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025-0700 Phone 336-548-8700 ● www.remington.com

TRANSMISSION VERIFICATION REPORT

NAME

07/26/2011 14:12

FAX

3365487823 TEL : SER.# : BROC0J148005

DATE, TIME FAX NO./NAME DURATION PAGE (S)

07/26 14:11 198969<u>7</u>3862 00:00:52 02 OK STANDARD

Remington.

FACSIMILE TRANSMITTAL SHEET Date: To: July 26, 2011 Ray Frank's Great Outdoors From: Dell Fulcher Company: Fax No.: 989-697-3862 Fax No.: 336-548-7872 Phone No.: Phone No.: 989-697-5341 1-800-243-9700 Press 0 and ask for ext 8686 Number of pages including Cover Sheet: 2 **COMMENTS:** Quote to repair