

Remington Arms Co., Inc.
Product Service
Legal Case #:6783

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
245434	11/1/2011	11/2/2011	11/2/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	McCoy Outdoor Co		McCoy Outdoor C	3498 Springhill Ave	Mobile	AL	36608		W 251-473-1080
Incident		Margaret	Miller	1704 Humber Ave	Mobile	AL	36604		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired on safe release	Concern:1007 Fired on Safe Release		
C				

11/16/11 Per note with rifle, this rifle has discharged as a result of moving safety to fire from safe position.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	n/a	A6658825	DQ	9/10/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	HICKS INC LUVERNE AL	SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	42.40	11/16/2011				

11/16/11 Per Ilion, could not duplicate concern. Trigger assm dirty and sticky, parts work sluggish. Replace TPA, clean, test fire at BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/2/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 243 WIN
	Date Code		DQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY PARTS WORK SLUGGISH
	Pull	---Select---	6.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

Remington Arms Service
14 Hoepler Ave.
Ilion NY 133571816



22"
DQ9/78
6.5#
1012

McCoy Outdoor Co., Inc.

3498 Springhill Avenue
Mobile, AL 36608
Phone-(251) 473-1080
Fax-(251) 473-3035

6783

Date 10-27-11

Make/Model

Customer Name Margaret Miller
Address 1704 Humber Ave
Mobile AL 36604
Phone _____

- ☐ Reel _____
☐ Rod _____
☐ Gun _____
☐ Optics _____
☐ Sunglasses _____
☐ Other _____

Notes

1- Rem 700 243
3/n A6658825
This rifle as discharged as a result of moving safety
to fire from safe position
Please repair as needed to make gun safe and
give detailed description of work done on gun.
could not duplicate concern Thanks,
T.A. daky & sticky parts Wesley Parks
work sluggish. replace
TPA, clean & test fire again
BCP for \$60.00 + ship
Quote

Received By: Wesley Parks
Date sent to Vendor: _____
Date Received from Vendor: _____
Called Customer to Pick-up: _____

Serial Number:

A6658825

Model: 700

BY: _____



RE00245434

RECEIVED

NOV - 8 2011

White • Store Copy / Yellow • Vendor Copy







