

Remington Arms Co., Inc.
Product Service
Legal Case #:6531

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
239779	9/1/2011	9/2/2011	9/2/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Dick's Sporting Goods		Dick's Sporting						
Incident		Ron	Misercola	925 GR 111					H 512-751-6101

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fired when bolt closed	Concern:1008 Fired on Bolt Closing		
C				

9/20/11 Per note with rifle, mis-fire. As customer locked the bolt down the gun fired without pulling the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/223 REM	85433	G6950850	AE	3/8/2010 1:31:25 PM

Date Purchased	Where Purchased	Accessories	Original Owner
	DICK S SPORTING GOODS/ATL	SCOPE,RINGS,TWO PIECE BASE,SLING	U

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, will replace TPA, clean, test fire at no charge under warranty						

Repair/Replacement Cost	Repair/Replacement Date
47.40	9/20/2011

9/20/11 Per Ilion, could not duplicate concern. To restore confidence in rifle, will replace TPA, clean, test fire at no charge under warranty.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/2/2011
	Product Type		RF

	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 223 REM HB
	Date Code		AE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Like new; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
Extractor	Stop	Like new; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		M/700 SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	N/A
	Notch	Like new; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SLING



FIREARM RECEIPT FORM

14332

 DROP OFF DATE 8/23/2011 PICK UP DATE 6531 STORE NUMBER 743
NAME Ron M. sercolaADDRESS 925 CR. 111TELEPHONE # (512) 751-6101IDENTIFICATION TYPE TX DL NUMBER 12937950EXPIRATION DATE 02/10/2014 DATE OF BIRTH (D.O.B.) 02/10/1968MANUFACTURER AND IMPORTER BemingtonMODEL 700 ADL CALIBER/GAUGE .223SERIAL # G6950850REASON FOR RETURN/DEFECTS: Mis fire. As customerlocked the bolt down the gunfired without pulling the triggerASSOCIATE SIGNATURE DROP OFF [Signature] PICK UP [Signature]CUSTOMER SIGNATURE DROP OFF [Signature] PICK UP [Signature]
 CUSTOMER DROPPING OFF AND PICKING UP THE FIREARM MUST BE THE SAME PERSON.
 PLEASE ALLOW 8-12 WEEKS FOR RETURN OF THE FIREARM.

PART 1 - STORE PART 2 - CUSTOMER PART 3 - ATTACH TO FIREARM

G6950850

Model: 700



RE00239779

could not duplicate concern
 to restore confidence in rifle
 will replace TPA, clean + test
 Rifle AT N/C

warranty

 RECEIVED
 SEP 08 2011

BY:

 26"
 AE 3/10
 5#





