Remington Arms Co., Inc. **Product Service** Legal Case #:5202

Case Information

RE# Date Opened(PS) **Date Opened Date Closed Incident Date** Pre Lit Lit Obsolete 12/1/2011 11/24/2010 248835 12/2/2011 11/23/2010

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact H 570-271-1750 402 Bald Top Rd. Danville PA 17821 Incident Clinton Myers E cmyers@phoenixcon.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4006 Altered Adjustments or Components

Concern:1007 Fired on Safe Release

Unknown

Serial

Bbl.

B6223961 OA 7/8/1980

DOM

S C FSR

11/24/10: Customer called in. He was hunting on 11/23/10 and stated that he had a FSR. No damage, No injury. He bought gun used & doesn't know if previous owner did anything to gun. df

Firearm Information

Mfg. Type Model/Ga. SKU CF/BA 700/7MM REM MA Remington n/a

Date Purchased Where Purchased Accessories Original Owner

ECON SPLY POTTSVILLE PA N

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Repair/Replacement Cost Date

> > \$30.40 12/12/2011

11/24/10: Sending ARS, ltr, form. df 7/15/11: Customer called & stated that he doesn't remember getting the above info & asked me to re-issue. df 12/12/11: Per Ilion - TA dirty & screws altered. Replace TA, clean & test fire under BLM - quote. Customer paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/2/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5202&Type=Case

12/12/2011

Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 7MM REM MAG
	Date Code		OA
	Bore Plugged	False	
	Bulged	False	-
	Fired	False	=
	Fired while Obstructed		· · ·
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	Ī
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
-	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
	g	Test Fired	False
Feeding Test	Tests False		
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY WILL FOLLOW DOWN
	Pull	Select	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

24" 047/ 3157

5202

CON

November 24, 2010

Clinton Myers 402 Bald Top Rd. Danville, PA 17821 Ph: 570-271-1750

Ref: #5202

Dear Mr. Myers,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

B6223961 Model: 700 RE00248835 T.A. dirty eset screws Altered.

Appear TPA, clear toot Pire under

BCP for \$ 20.00 + ship

Quote ECETVE DEC 0 6 2011

. . . i

BY.

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 ● www.remington.com

Print

Reset

Model Number: 305 0 600 MAC	Serial					
Number: 300 7mm R6n MAG Number: B6223961						
Are you the original owner?: YES X NO						
Name: Clinton Myers	Date of Purchase:					
Address (no PO Boxes): 402 Bald Top Rd						
City: Danville	State: <i>PA</i> Zip: /782/					
Phone (Daytime): 5つ0ー2フェーノフェロ	Fax:					
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) Cmyers & phoenix Con . Com						
E-mail A						
🗵 I would like to receive future e	e-mail updates from Remington.					
Please describe your proble	em and date of occurrence:					
Firearm went off 2 times over 2 yrs when safety was removed when soins to eyect shell in chamber. Last occurance was 11/10, Please Remove broken screw and front scope mount hole. Broke screw when setting ready to return gun. 500 characters left						
Ammunition I	nformation:					
Manufacturer: Reminstan	Type: RDMM2					
Other (i.e. bullet weight/type, shot size, powder): ISOGV Soft PE						
Handload Information:						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used:					
Firearms Care (Cleaning and Lubrication):						

Brand of cleaning solution used: Kenington Oil				
How often do you clean the bore? (Months or Number of rounds) After use, 3 this ye				
How often do you clean the action? (Months or Number of rounds) After use, 3 times you				
How often do you clean the trigger assembly? (Months or Number of rounds)				
Brand of lubricant used: Renisstan 0.1				
How often do you lubricate the bore? (Months or Number of rounds)				
How often do you lubricate the action? (Months or Number of rounds)				
How often do you lubricate the trigger assembly? (Months or Number of rounds) 5 and as above				
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☒ YES ☒ NO				
When was the last time that your firearm was serviced by a Remington authorized				
What were the services performed?)				
Ship your INSURED firearm by either UPS or Parcel Post to:				
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357				
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN				
THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/24/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXXX Valentia altridustry (17)
DESCRIPTION:	Ref # 5202 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Clinton Myers
402 Bald Top Rd.
Danville, PA 17821
Ph: 570-271-1750

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

1st label

4XX596 NOV 29 2010 ALL CURR USD 1 0F 1 SVC GNDCOM ACT WT 10.0 LBS

TRACKING# 1Z4XX5969067189121
REF 1:CLINTON MYERS/CD/DMF

REF 2:5202/RIFLE

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 7.42 PUB+HANDLING 7.42







