Page 1 of 2 **PrintDisplay**

> Remington Arms Co., Inc. Product Service Legal Case #:6366

Case Information

Date Opened(PS) RE# Date Opened **Date Closed Incident Date** Pre Lit Obsolete 7/13/2011 7/18/2011 7/19/2011 235570

Customer Information

Type Business First Name Last Name Street City State Zip Contact 200 Pheasant Dr Incident John O'Brien Mapleville RI 02839 H 401-568-3185

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status

PΙ

PD Altered Adjustments or Cause:4006

Components Unknown Fires when safety is released at

times

Concern: 1007 Fired on Safe Release

S C

7/22/11 Per note with rifle, when cocked will fire when safety is putoff. Not all the time.cm

Firearm Information

CONCERN:FSR

Type Model/Ga. SKU Bbl. DOM Mfg. Serial ML/BA 700/50 CAL 27580 ML040143 11/15/1996 Remington RQ Date Purchased Where Purchased Accessories **Original Owner** Ν

JERRYS SPORT CENTER INC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/ML/BA

Cash Reim. Cash Settlement Release of Claims Release Date Reimbursement Settlement Date APV Date APV

Per Ilion, replace TPA, clean and check over at 1/2 normal cost

> Repair/Replacement Repair/Replacement Date

7/22/11 Per Ilion, trigger assm dirty and set screws altered. Trigger will not return properly. Replace TPA, clean and check over at 1/2 normal cost.cm

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/19/2011
	Product Type]	RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 50 CAL SS
	Date Code]	RQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6366&Type=Case

7/22/2011

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Select	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tesis	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, TRIG NOT RETURNING WILL FOLLOW DOWN
	Puil	Select	1.5#
	Altered	True	SET SCREWS ALTERED

6366

24"
Ra1196

Remington.

Factory Repair Instructions

	olete this form, and then include it	t with your firearm.)	
Model Number: 700 ML	Serial Number: //	1L 040/43	
Are you the original owner?: YES	V eno	,	
Name: John OBrien	···	Date of Purchase:	
Address (no PO Boxes):			
200 PhEASANT DR			
city: MAPICVILLE	State: RI	Zip: 02839	
Phone (Daytime): 401- 568-3.	/85 Fax:		
E-mail Address: Would like to receive future e-mail upon	and the second of the second o		
Please describe your problem:			
When Cocked will	FIRE When SAF	ety is Put	
OFF. NOT All The			
		DECETIVE.	
	and the second s		
Ammunition Information:	, w. 1	LL JUL 2 0 ZUT	
Manufacturer:	Type:	- 5.4	
Other (i.e. bullet weight/type, shot size, pow	der):	D1.22	
	s the second section of the second	· · · · · · · · · · · · · · · · · · ·	
Handload Information:	a.t.		
Powder Used: Pyrodex	Powder Weight:	1009.	
Case/Hull Used:	Primer Used:	209	
Bullet Type/Shot Size:	Reloader Used:		
Firearms Care (Cleaning and Lubrication);		
Brand of cleaning solution used:	Hoples		
How often do you clean the bore? (Months or		10 Shots	
How often do you clean the action? (Months	7	4m r	
How often do you clean the trigger assembly	? (Months or Number of rounds)		
	Neu	res	
Brand of lubricant used: WD 40			

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

工作专数搬剿 50%。宝山位于

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

Ship your INSURED firearm by either UPS or Parcel Post to:

REMINGTON ARMS CO., INC

ATTN: Arms Service Diviso 14 Hoefler Ave Ilion, NY 13357

ML040143 Model:



YOUR FIREARM OR IN THE SAME BOX WITH THE IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND

mage in shipping and handling. Preferably, e returned.)

bss or damage.

ele the box. Shipments without a proper

st. Remington is not responsible for. purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

> T. A. Jirty + set screws Altered Tiziq. Will not return properly.
>
> Replace TOA, clear a check over
>
> At # 1/2 Moranal cost.







