

Remington Arms Co., Inc.
Product Service
Legal Case #:7067

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
250158	12/13/2011	12/14/2011	12/14/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Olde English Outfitters	---	Olde English Ou	480 E. Ginghamburg Rd	Tipp City	OH	45371		W 937-667-3315

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Dealer sent gun in for consumer. Dealer stated rifle fires when safety lever is engaged. No damage or injury reported. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	27450	S6457412 RW		11/11/2002 9:33:48 AM

Date Purchased	Where Purchased	Accessories	Original Owner
	ACUSPORT (OH) CORPORATION	TWO PIECE BASE	U

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						

Repair/Replacement Cost	Repair/Replacement Date

12/16/11: Per Ilion - TA set screws altered. TA is not returning under sear. Replace TA, clean & test fire at 1/2 normal cost - quote. Quote was apprvd & paid. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/14/2011
	Product Type		RF
	Action Type		A

	Assigned To	T.NAGLE	
Cause	4006	Altered Adjustments or Components	
Barrel	Description		26" 22-250 REM HB SS
	Date Code		RW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	N/A
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

7067

26"
RW 11/02

12/6/11

Remington Arms

Please repair M700
S 6457412.

> Rifle fires when
safety lever engaged.

(Close bolt - engage safety)
Gun fires

No one was
hurt.

Thank you
Mitch English

RECEIVED
DEC 16 2011

480 E. Ginghamburg Road • Tipp City, OH 45371 • 937-667-3315

BY:

Serial
Number:

S6457412

Model: 700



RE00250158

T.A. set screws altered. Trig. is
not returning under seal.
Replace TPA, clean test fire
at 1/2 normal cost.

Quake







