Remington Arms Co., Inc. Product Service Legal Case #:7075

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

258665 2/15/2012 12/14/2011 2/16/2012

Customer Information

Business First Name Last Name Street City Contact Type State Zip Age H 814-635-3933 138 Nutmeg Rd Incident Todd Ross Saxton PA 16678 W 1-800-432-0680 x 142

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status** 

ΡI

PD Cause: 4015 Improper Maintenance

Unknown Concern: 1008 Fired on Bolt Closing

S FBC C

12/13/11: Customer called in. He stated in has had a FBC twice in cold weather. No injury or damage reported. df

Firearm Information

Model/Ga. Mfg. SKU Type Serial Bbl. DOM 700/270 WIN Remington CF/BA n/a A6500373 DO 9/1/1977

**Date Purchased** Where Purchased Accessories Original Owner N

OUTDOOR SPORTS DAYTON OH TWO PIECE BASE CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion - Ouote to repair under BLM

> Repair/Replacement Repair/Replacement Date Cost

12/14/11: Mailing ARS & forms. df 2/20/12: Per Ilion - TA dirty, parts binding, set screws altered. Replace TA, clean & test fire under BLM quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		2/16/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	SET SCREWS ALTERED
	Description		22" 270 WIN
	Date Code		DO
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7075&Type=Case

2/27/2012

		,	
	Condition	Slightly Worn; Functioning	,
	Firing Pin	Slightly Worn; Functioning	]
	Shroud	Slightly Worn; Functioning	]
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	·
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	· · · · · · · · · · · · · · · · · · ·
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
-	Lift	Select	.007
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	16202	False	
, <u></u>	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,PARTS BINDING WILL FOLLO DOWN
Trigger	Pull	Select	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	·
Non-Remington Components	Description		TWO PIECE BASE

72.1' D09/7 4.5'

-1075

December 14, 2011

Todd Ross 138 Nutmeg Rd Saxton, PA 16678

Phone: 800-432-0680 x 142

Ref: #7075, Model 700, Serial # A6500373

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

Model: 700 RE00258665 T.A. dinky pants is unding, set screws of tered. My hau TRA, cleant rest under BLP for to to. +

FEB 2 0 2012

Quote

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

## Service Request

## Remington Service PO Box 700

ce



Date of Request:

Printed:

12/14/2011

12/14/2011

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

ATTN: Product Service

Date

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number

Serial Number / Description

A6500373

Model 700 Center Fire Caliber: 270

Customer: TODD ROSS 138 NUTMEG RD

SR00006735

SAXTON, PA 16678 US

Destination:

Email:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section ....

Product Service # 7075

Parts And Service Details

Material Type

Description

Qty Needed Warranty

Pr

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

. 00

Est Sales Tax:

.00

**Grand Total:** 

\$.00

	_	_		
Æ	Ιv	١in	٠.	
•	-1	11	11	

D	
KASAT	
いたのない	

Model	Serial				
Number: 700 BDL LH Number: A6500373					
Are you the original ow	ner?: LI YES JA NO				
Name: TODD ROSS	Date of Purchase:				
Address (no PO Boxes):					
City: SAXTON	State: PA Zip: 16678				
Phone (Daytime): 814-635-3933					
E-mail Address:(if e-mail address is provided be sent)					
E-mail A ⊠ I would like to receive future e	ddress:				
Please describe your problem and date of occurrence:  - RIFLE WILL NOT FINE BELOW 25°F DEC. 2008 & DEC. 2010					
- RIFLE HAS GONE OFF (FARED) WHEN ENGAGING BOLT ACTIONS DEC. 1997 & DEC. 2010.					
500 cha	racters left				
Ammunition I	nformation:				
Manufacturer: REMINGTON	Type: CORE-LOK 130 GLAIN				
Other (i.e. bullet weight/type, shot size, powder):					
1111.6					
Powder Used: Powder Weight: 1/4/15					
Powder Used: Nows	Primer Used:				
Rullet Type/Shot Size:	Reloader Used:				
Dullet Type/Silot Size.					
Firearms Care (Cleaning and Lubrication): RIM OIL					

http://www.remington.com/asp/factory\_repair\_form.asp

8/25/2011

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) SUCLY YEAR.
How often do you clean the action? (Months or Number of rounds) EVERY GEAR
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Rim oil
How often do you lubricate the bore? (Months or Number of rounds) EUERY YEAR.
How often do you lubricate the action? (Months or Number of rounds) EUERY YEAR
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES ☑ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) NEVER
What were the services performed?) NONC
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

http://www.remington.com/asp/factory\_repair\_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

CONTACT ME AND I CAN SEND YOU A CHECK. I CAN ALSO GIVE YOU MY CREDIT CARD NUMBER AT THAT TIME.

1000 ROSS

## ARS LABEL REQUEST FORM

DATE:	12/14/2011	Service Request #	SR00006735
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY: fulcherdm		email address:	I WILL MAIL LABEL

**Business:** 

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

## LABEL INFORMATION

MAIL LABEL TO:

TODD ROSS 138 NUTMEG RD SAXTON, PA 16678 US SR00006735

Email:

**RETURN ITEM TO:** 

ILN

Arms Services



ATTN: Product Service

4XX596 DEC 16, 2011 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969065641831 ALL CURRENCY USD REF 1:SR00006736 REF 2:

HANDLING CHARGE 0.00 FRT: 3RD
SHIPMENT PUB RATE CHARGES: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00
AH 0.00 PR 0.00 ROD 0.00
TOT PUB CHG 8.16 PUB+HANDLING 8.16







