Remington Arms Co., Inc. Product Service Legal Case #:6990

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete Lit 12/15/2011 250590 12/5/2011 12/16/2011

Customer Information

Business First Name Last Name Street Zip Contact Type City State Age 3915 Elk River Rd Incident David Samples Gassaway 26624 H 304-364-5487

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause:4015 Improper Maintenance

Unknown Concern:1008 Fired on Bolt Closing

S

12/5/11 Per call from Samples, his rifle will fire when he closes the bolt.cm

Firearm Information

Fired when closing bolt

Mfg. Model/Ga. SKU DOM Type Serial Bbl. Remington CF/BA 700/7MM REM MA n/a B6281696 XA 12/10/1980

Date Purchased Where Purchased Original Owner Accessories

M W DIST NITRO WV TWO PIECE BASE Y

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Cash Settlement Release of Claims Release Date Reimbursement Settlement Date APV Date APV

Per Ilion, replace TPA, clean, test fire at BLSM program price

> Repair/Replacement Repair/Replacement Date

Cost 30.26 12/28/2011

12/5/11 Mailing ARS.cm 12/28/11 Per Ilion, could not duplicate concern. Trigger assm very dirty. Can offer to replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part Sub-Part		Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		12/16/2011	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4015	Improper Maintenance		
	Description		24" 7MM REM MAG	
	Date Code		XA	
	Bore Plugged	False		
Barrel	Bulged	False		
	Fired	False		
	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		

http://cns03an13:200/nsaann/PrintDisnlay asny?ID=6990&Tyne=Case

12/28/2011

	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	·
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Select	AFT MKT B&C STK
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	
	Т	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	VERY DIRTY
Tiere	Pull	Select	4.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Remington.

24" X A12/80 4.5%

6990

December 5, 2011

David Samples 3915 Elk River Rd Gassaway, WV 26624

Subject: Case # 6990, Model 700, SR# 5697


Dear Mr. Samples,

Please include a copy of this letter with the firearm as well as the Service Request form. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the small ends of the box "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com





could not dyplicate concern T. A. very dinty. can offer to replace TPA, clean + Test fine under BCP Ron \$ 20. + Ship Onde

Remington Arms Company, Inc. ◆ 870 Remington Drive ◆ P.O. Box 700 ◆ Madison, NC 27025 Phone 800-243-9700 ◆ www.remington.com

Service Request

WITH YOUR RETURN.

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Product Service #6990

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT

Service Request Number Serial Number / Description 12/05/2011 Date of Request: SR00005697 B6281696 12/05/2011 Date Printed: Model 700 Customer: Destination: **DAVID SAMPLES** Arms Services 3915 ELK RIVER RD 14 Hoefler Ave GASSAWAY, WV 26624 US Ilion, NY 13357 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Fired when closing the bolt.cm

Parts And Service Details Material Type

Description

Qty Needed Warranty

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Model Number: 700	Serial Number: 8628/696		
Are you the original owner?: YES NO			
Name: David L. Sample & 0	Date of Purchase; Lake 1480 ?		
Address (no PO Boxes): 3915 Elk River	. Rd		
City: GASBAWAY	State: WV, Zip: 16624		
Phone (Daytime): 304-344-5487	Fax:		
E-mail Address:(if e-mail address is provided, notification	n of receipt end shipment will be		
senti)			
E-mail Address:			
i would like to receive future e-mail updates from Re	- 		
Please describe your problem and date of occurrence	e:		
When Empting Chamber, the Rifle			
went off about & different times when			
closeing Bolt, Last incident was			
Last week: 12-1-	- 3011,		
	the state of the s		
contract early			
500 cherecters left			
Ammunition Information:			
Manufacturer. Remington	Type: Core-lock		
Other (i.e. bullet weight/type, shot size, powder):	50 grains		
Handload Information:			
Powder Used:	Powder Weight:		
Case/Hull Used:	Primer Used:		
Bullet Type/Snot Size:	Reloader Used:		

	Firearms Care (Cleaning and Lubrication):					
1	Brand of cleaning solution used: Hoppe's					
	How often do you clean the bore? (Months or Number of rounds) After Each Jeason I didn					
How often do you clean the action? (Months or Number of rounds)						
How often do you clean the trigger assembly? (Months or Number of rounds)						
Brand of Jubricant used:						
How often do you lubricate the bore? (Months or Number of rounds)						
age on the second	How often do you lubricate the action? (Months or Number of rounds)					
	How often do you lubricate the trigger assembly? (Months or Number of rounds)					
	Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? The year of the cleaning and maintenance recommendations on our web site or in our owners manual? The year of the cleaning and maintenance recommendations on our web site or in our owners manual?					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) What were the services performed?)						
					Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefier Avenue Illon, NY 13357	
	THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.					
	:: Record the serial number of your firearm before sending it. I! Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage, :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.					

ARS LABEL REQUEST FORM

DATE:	12/05/2011	Service Request #	SR00005697
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelles	email address:	Christy Mitchell@remington.com
			•

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

DAVID SAMPLES 3915 ELK RIVER RD GASSAWAY, WV 26624 US SR00005697

Email:

RETURN ITEM TO:

ILN

Arms Services





1 OF 1 DEC 5, 2011 ALL CURR USD ACT UT 10.0 LBS 4XX596 SVC GNDCOM TRACKING# 1Z4XX5969067750371 REF 1:SR00005697 REF 2: HANDLING CHARGE 0 00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 0.00 COD SD 0.00 00.0 VC 0.00 DC 0.00 AH 0.00 TOT PUB CHG 9.04 DGD 0.00 SP 0.00 PR PUB+HANDLING 9.04



