

Remington Arms Co., Inc.
Product Service
Legal Case #:6647

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
242537	10/5/2011	10/6/2011	10/6/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Schiedler	13258 Portland Rd NE	Gervais	OR	97026		H 503-792-4469 F 503-792-3774

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when closing bolt	Cause:4006 Altered Adjustments or Components Concern:1008 Fired on Bolt Closing	Unknown	
C				

10/14/11 Per note with rifle, this gun has fired when he closed the bolt with a round in the chamber.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	n/a	6485208	EU	10/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	NAVY RESALE BROOKLYN NY	TWO PIECE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test fire under BLSM price						
	Repair/Replacement Cost	Repair/Replacement Date				
	45.40	10/14/2011				

10/14/11 Per Ilion, trigger assm dirty, trigger not returning properly, set screws altered. Replace TPA, clean, test fire under BLSM price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/6/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		24" 7MM REM MAG
	Date Code		EU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG SLUGGISH, NOT RETURNING PROPERLY WILL FOLLLOW DOWN
	Pull	---Select---	5#
	Altered	True	SET SCREWS ALTERED

	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Serial Number:

6485208

Model: 700



RE00242537

6647

24"
EU 10/1
5#
1011

Larry & Laura Schiedler
13258 Portland Rd. NE
Gervais, OR 97026
503-792-4469
(Fax) 503-792-3774

To: Remington Arms From: Larry Schiedler
Fax: _____ Pages: T.A. dirty, TRIP. NOT RETURNING
Phone: _____ Date: properly, set screws altered.
Re: _____ Time: Upgrade TPA, CLEAN + TEST Rine
UNDER BLP FOR \$20.00 + skip
Quote

☐ Urgent ☐ For Review ☐ Please Comment ☐ Please Reply

I called your location and was told my rifle
(700 BDL) qualified for the Safety modification program.
So I am sending it in to you. I will follow
this up with a phone call in a week or so to make
payment of approx. \$37⁰⁰ as instructed when I called.
If you have any questions, my phone + fax is listed
above and my cell # is 503 551-6765.

Thank you

Larry Schiedler
Larry Schiedler

Problem:

This gun has fired on me before
when I closed the bolt with a round
in the chamber.

RECEIVED
OCT 07 2011

BY:.....







