

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7049

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 249916 | 12/12/2011  | 12/13/2011      | 12/13/2011  |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street         | City       | State | Zip   | Age | Contact |
|----------|----------|------------|-----------|----------------|------------|-------|-------|-----|---------|
| Incident |          | Loran L    | Shields   | 38 Lakeview Dr | Cloudcroft | NM    | 88317 |     |         |

## Incident Information

| Claims | Codes             | Repair Est.                 | Medical Treatment                                     | Medical Status |
|--------|-------------------|-----------------------------|---|----------------|
| PI     |                   |                             |   |                |
| PD     | Cause:4038        | Could Not Duplicate Concern |   |                |
| S      | Fired on it's own | Concern:1025                | Unexplained Discharge - No Mention of Safety Position | Unknown        |
| C      |                   |                             |   |                |

1/16/12 Per letter with rifle, this is a one owner gun purchased new in 1970. While hunting with his two sons in 1973, this gun fired of it's own accord, barely missing my youngest son. Since that time he has not attempted to use the gun fearing another accident.cm

## Firearm Information

| Mfg.           | Type            | Model/Ga.     | SKU            | Serial | Bbl. | DOM      |
|----------------|-----------------|---------------|----------------|--------|------|----------|
| Remington      | CF/BA           | 700/3006 SPRG | n/a            | 294251 | OP   | 7/1/1967 |
| Date Purchased | Where Purchased | Accessories   | Original Owner |        |      |          |
|                |                 |               | Y              |        |      |          |

CONCERN:FIRE ON IT'S OWN

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

| Settlement   | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|--|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Can offer to replace TPA, clean, test fire at BLSM program price |                         |                         |               |                 |                |               |
|  | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|  | 30.40                   | 1/16/2012               |               |                 |                |               |

1/16/12 Per Ilion, could not duplicate concern. Trigger assm dirty and sticky. Can offer to replace TPA, clean, test fire at BLSM program price.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                        | Comment       |
|-------------|--------------|-----------------------------|---------------|
| Examination | Examiner     |                             | B.TRAVIS      |
|             | Exam Date    |                             | 12/13/2011    |
|             | Product Type |                             | RF            |
|             | Action Type  |                             | A             |
|             | Assigned To  |                             | T.NAGLE       |
| Cause       | 4038         | Could Not Duplicate Concern |               |
| Barrel      | Description  |                             | 22" 3006 SPRG |
|             | Date Code    |                             | OP            |
|             | Bore Plugged | False                       |               |
|             | Bulged       | False                       |               |
|             | Fired        | False                       |               |

|              |                        |                            |                        |
|--------------|------------------------|----------------------------|------------------------|
|              | Fired while Obstructed |                            |                        |
|              | Muzzle/Crown Condition | Slightly Worn; Functioning |                        |
| Bolt         | Firing Pin             | Slightly Worn; Functioning |                        |
|              | Shroud                 | Slightly Worn; Functioning |                        |
|              | Face                   | Slightly Worn; Functioning |                        |
|              | Handle                 | Slightly Worn; Functioning |                        |
|              | Stop                   | Slightly Worn; Functioning |                        |
| Extractor    | Condition              | Slightly Worn; Functioning |                        |
|              | Cut Condition          | Slightly Worn; Functioning |                        |
|              | Ext/Eject Test         | False                      |                        |
| Locking      | Block Condition        | ---Select---               |                        |
|              | Lug Condition          | Slightly Worn; Functioning |                        |
|              | Notch Condition        | ---Select---               |                        |
| Overall      | Exterior Condition     | Slightly Worn; Functioning |                        |
|              | Stock Condition        | Slightly Worn; Functioning |                        |
|              | Fore End Condition     | ---Select---               |                        |
| Receiver     | Condition              | Slightly Worn; Functioning |                        |
|              | Bulged                 | False                      |                        |
| Safety       | Description            |                            | M/700 BOLT LOCK SAFETY |
|              | Function               | Like new; Functioning      |                        |
|              | Sub-Assembly           | Non-ISS                    |                        |
| Sear         | Lift                   | ---Select---               | .002                   |
|              | Notch                  | Slightly Worn; Functioning |                        |
|              | Tests                  | Test Fired                 | False                  |
| Feeding Test | Tests                  | False                      |                        |
| Trigger      | Condition              | Slightly Worn; Functioning | DIRTY,STICKY           |
|              | Pull                   | ---Select---               | 3.5#                   |
|              | Altered                | False                      |                        |
|              | Sub-Assembly           | M/700 Bolt Lock            |                        |

22"  
0P7/6  
3.5"  
002

7049

December 2, 2011

Remington Arms Company, Inc.  
870 Remington Drive  
P. O. Box 700  
Madison, NC 27025-0700

RE: Recall for Model 700-ADL-30-06 Rifle: Serial 294251

To Whom It May Concern:

This is a one owner gun, as I purchased it in new in 1970. While hunting with my two sons in 1973, this gun fired of its' own accord, barely missing my youngest son. Since that time, I have not attempted to use the gun, fearing another accident.

I contacted Remington in January of 1976 and explained the incident to the representative. I was told there was nothing wrong with the gun and it had to be because of something we had done. I let the matter drop as I knew of no alternative. I own a number of Remington firearms, and this is the only one I have had a problem with.


I have become aware of your recall of this model, and so am sending the gun to you for repair. Up until the time of the first incident, I had regularly cleaned and maintained the gun (as I do all my firearms). Since that time, I have neither fired or used the gun in any way.

Please repair this rifle and return it to:

Loran L. Shields  
38 Lakeview Drive  
Clondcroft, NM 88317

Thank you.

Yours truly,

  
Loran L. Shields

Enc.

RECEIVED  
DEC 16 2011  
BY: \_\_\_\_\_

Serial Number

294251

Model: 700



RE00249916

could not duplicate concern  
T.A. dirty & sticky. can often to  
replace TPA, clean test rifle  
under DLP for 20. + ship

Quote



