

Remington Arms Co., Inc.
Product Service
Legal Case #:6966

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
248694	12/1/2011	12/2/2011	12/2/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Shooter's Supply		Shooter's Suppl	PO Box 26	Lomira	WI	53048		W 920-269-4995

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Fires on bolt closing, fails to cock	Concern:1008 Fired on Bolt Closing	Unknown	
C				

12/26/11 Per note with rifle, gun fires when closing bolt. Fails to cock.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	20000	361101	WR	8/1/1968
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA


Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Can offer to replace TPA, clean and test fire under BLSM						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	12/26/2011				

12/26/11 Per Ilion, trigger assm dirty, sticky and sear is sticking to side plates. Can offer to replace TPA, clean and test fire under BLSM for \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/2/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		WR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY SEAR BINDS TO SIDEPLATES WILL FOLLOW DOWN
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE



6966

22"
WR 8/68
4.5#

~~Drivers License~~

QUAN	DESCRIPTION	PRICE
	M-700 CAL 30-06 BDL #361101 W/ SCOPE BASE	
	GUN FIRES WHEN CLOSING BOLT FAILS TO COCK	
	PLEASE REPAIR	
	THANKS	

TERMS: DUE UPON RECEIPT SIGNED:

SIGNED: P. Schadel

TP.T.120

361101

Model: 700



RE00248694

T.A. dirty, sticky & seal is sticking to side plates. Can offer to replace TPA, clean & test fire under BLP for \$20.00 + ship

Quake

