Remington Arms Co., Inc. **Product Service** Legal Case #:6957

Case Information

RE#

Date Opened(PS) **Date Opened** 

**Date Closed** 

**Incident Date** 

11/29/2011

Customer Information

Type

Business First Name Last Name

Street

City State Zip Age Contact

Obsolete

Incident

Tommy

Skinner

12/1/2011

544 Lone Mountain Rd

Ardmore OK 74301

H 580-222-5488

Incident Information

Claims

Codes

Repair Est. Medical Treatment Medical Status

Pre Lit Lit

PΙ

PD Shot hole in floorboard of

truck

Cause:4079 Other - Unexamined Concern:1008 Fired on Bolt Closing

Unknown

73401

S

C

12/1/11 Per call from Skinner, he was loading his rifle in his pickup and it fired when he closed the bolt. He had not had problems with the rifle prior.cm

Firearm Information

Mfg.

Type

Model/Ga.

**SKU** 

Serial Bbl.

**DOM** 

Remington

CF/BA

700/270 WIN

27317 F6262741 3/17/2003 2:44:05 PM

**Date Purchased** 

Where Purchased

Accessories Original Owner

ACUSPORT (MT) CORPORATION

N

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV

APV

Repair/Replacement

Cost

Repair/Replacement Date

12/1/11 Mailing ARS.cm

Examination[Remington/CF/BA]

Sub-Part Code Part Comment

## ARS LABEL REQUEST FORM

DATE:	12/01/2011	Service Request #	SR00005460
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchellcs	email address:	Christy.Mitchell@remington.com

**Business:** 

Remington Service PO Box 700

Madison, NC 27025-0700 www.Remington.com

## LABEL INFORMATION

MAIL LABEL TO:

TOMMY SKINNER
544 LONE MOUNTAIN RD
ARDMORE, OK 74301 US
SR00005460 73401 73401

Email: Christy

**RETURN ITEM TO:** 

ILN

Arms Services



4XX596 SVC GNDCOM 4XX596 DEC 2, 2011 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969065427957 1 OF 1

REF 1:SR00005460 REF 2:

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 DC 0.00 COD 0.00 RS 0.50 DGD 0.00 SD 0.00 AH 0.00 0.00 SP 0.00

TOT PUB CHG 10.27

PUB+HANDLING 10.27

ATTN: Product Service #6957