

Remington Arms Co., Inc.
Product Service
Legal Case #:6563

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
240453	9/13/2011	9/14/2011	9/14/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Thomas	Srokosz	4213 Meadow Dr	Grapevine	TX	76051		H 817-366-6702

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired on safety release	Cause:4006 Altered Adjustments or Components Concern:1007 Fired on Safe Release	Unknown	
C				

9/27/11 Per note with rifle, when you cock and put on safety, then push safety forward the rifle can go off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	n/a	A6637775	XY	2/7/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	OUTDOOR SPT HQ GRD PRAIRIE TX		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	45.40	9/27/2011				

9/27/11 Per Ilion, trigger assm dirty and sticky, set screws altered. Replace TPA, clean, test fire at BLSM program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/14/2011
	Product Type		RF
	Action Type		A

	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	ALSO BBL HAS BEEN TURNED/REQUALIFIED IN RECEIVER
Barrel	Description		24" 7MM REM MAG
	Date Code		XY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	METAL RUSTY,PITTED
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY.TRIG NOT RETURNING PROPERLY. EXCESSIVE OVERTRAVEL
	Pull	---Select---	2.5#

	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

24"
X712/74
2.5"
.007

6563

Dear Sir,

I contacted your service dept about this rifle. When you cock and put on safety, then push safety forward the rifle can go off.

The person that I talked to said there was a safety upgrade. To look at the rifle, clean and do repairs was \$20 plus shipping.

Serial # A6637775

you can contact me by phone
817-366-6702

If I can't get to the phone leave a call back number and ext. #

RECEIVED
SEP 20 2011
BY:.....

Name - THOMAS SPOKOSZ
4213 MEADOW DRIVE
GRAVINE TEXAS 76051

T.A. dirty + sticky, set screws
Altered. Replaced TPA, CGAU +
rest Riva under BCP RoR
\$20.00 + ship
Q wta

Serial Number:

A6637775

Model: 700



RE00240453

Thank you
Thomas Spokosz









