

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6624

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
241890	9/27/2011	9/28/2011	10/10/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	T&T Gunnery	---	T&T Gunnery	3778 Merrick Rd.	Seaford	NY	11783		W 516-221-7380 F 516-221-7948

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C	FBC			

Dealer sent gun in for consumer. Dealer stated that rifle will occasionally fire by itself when a round is put into chamber. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	A6503462	DO	9/1/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	HARVAN SPTG NEW YORK NY	TWO PIECE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	10/10/2011				

10/10/11: Per Ilion - Could not duplicate concern. Can offer to replace TA, clean & test fire under BLM - quote. Tony @ store & consumer apprvd & pd by credit card. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/28/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	

Barrel	Description	22" 270 WIN
	Date Code	DO
	Bore Plugged	False
	Bulged	False
	Fired	False
	Fired while Obstructed	
	Muzzle/Crown Condition	Slightly Worn; Functioning
Bolt	Firing Pin	Slightly Worn; Functioning
	Shroud	Slightly Worn; Functioning
	Face	Slightly Worn; Functioning
	Handle	Slightly Worn; Functioning
	Stop	Slightly Worn; Functioning
Extractor	Condition	Slightly Worn; Functioning
	Cut Condition	Slightly Worn; Functioning
	Ext/Eject Test	False
Locking	Block Condition	---Select---
	Lug Condition	Slightly Worn; Functioning
	Notch Condition	---Select---
Overall	Exterior Condition	Slightly Worn; Functioning
	Stock Condition	Slightly Worn; Functioning
	Fore End Condition	---Select---
Receiver	Condition	Slightly Worn; Functioning
	Bulged	False
Safety	Description	M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning
	Sub-Assembly	Non-ISS
Sear	Lift	---Select---
	Notch	Slightly Worn; Functioning
	Tests	Test Fired
Feeding Test		False
Trigger	Condition	Slightly Worn; Functioning
	Pull	---Select---
	Altered	False
	Sub-Assembly	M/700 Bolt Lock
Non-Remington Components	Description	TWO PIECE BASE

6624

22"  
DO 9/77  
7#  
1010

**T&T GUNNERY**  
ATT: TONY  
**3778 MERRICK ROAD**  
**SEAFORD, NY 11783**  
516-221-7380 FAX 516-221-7948

TO: Remington

THE FOLLOWING HANDGUN / LONG GUN

MAKE: Remington  
MODEL: 700 LH  
SERIAL #: A6503462  
CALIBER: \_\_\_\_\_  
BARREL: \_\_\_\_\_  
ACCESSORIES: \_\_\_\_\_

DESCRIPTION OF REPAIR:  
① Rifle occasionally fires by itself  
when a round is put into chamber

Serial Number:

A6503462

Model: 700



RE00241890

REPAIR#: 2490

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

could not duplicate concern.  
CAN often to replace TPA,  
clean + test fire under BCP  
Return \$20.00 + ship

RECEIVED  
OCT 04 2011

Quote

BY: \_\_\_\_\_









