Remington Arms Co., Inc. Product Service Legal Case #:6829

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Obsolete Pre Lit Lit 11/29/2011 248249 11/28/2011 11/11/2011

Customer Information

Street State Type Business First Name Last Name City Zip Age Contact Keith 10961 Desert Lawn Dr #465 Calimesa CA 92320 H 909-446-0868 Incident Taylor

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4006 Altered Adjustments or Components Unknown

Concern:1007 Fired on Safe Release S

C FSR

11/11/11: Customer called. He stated that he had a FSR w/rifle. He did not have an incident date. No damage, No injury. He stated that rifle hasn't had a full box of shells through it - it's like new. df

Firearm Information

Mfg. Model/Ga. SKU Bbl. DOM Type Serial CF/BA 700/270 WIN 25791 B6896308 DH 9/28/1987 Remington

Date Purchased Where Purchased Accessories Original Owner

BEST PRODUCTS #202 Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Date Date Reimbursement Settlement APV APV

Per Ilion -Quote to repair

> Repair/Replacement Repair/Replacement Cost Date

11/11/11: Mailing ARS & forms. Box sent from Madison office. df 11/30/11: Customer called in. I don't have my report yet but went over what Ilion found. He was not happy & said that he would pay the quote when he got it in the mail & then do some follow up with other people. df 12/12/11: Per Ilion - TA set screws altered. Trigger not returning properly. Replace TA, clean & test fire @ 1/2 normal cost - quote. Customer paid quote. df


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
\	Examiner		B.TRAVIS
	Exam Date	•	11/29/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
			1

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6829&Type=Case

12/12/2011

Cause	4006	Altered Adjustments or Components	
Barrel	Description]	22" 270 WIN
	Date Code]	DH
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	· ·
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select]
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	6#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	



REITH TAYLOR
10961 DESERT LAWN DR #465
RS

SHIP TO:
PRODUCT SERVICE
ARMS SERVICES
14 HOEFLER AVE
ILION NY 13357

WY 135 0-01


UPS GROUND
TRACKING #: 1Z 4XX 596 90 6538 6760

B6896308 Model: 700

RE00248249

T. A. Set screws Altered. Thig. Not returning properly, Replace TPA, clears test fire AT 1/2 Normal Cost.

Quete



ARS LABEL REQUEST FORM

DATE:	11/11/2011	Service Request #	SR00003516
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
D!			

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

KEITH TAYLOR 10961 DESERT LAWN DR #465 CALIMESA, CA 92320 US SR00003516

Email:

RETURN ITEM TO:

ILN

Arms Services



NOV 15, 2011 ALL CURR USD ACT WT 10.0 LBS 4XX596 NOV 15, 2011 SVC GNDCOM ACT WT TRACKING# 1Z4XX5969065499095 REF 1:SR00003516

SINGLE-PIECE PUB RATE CHRGS: DV 0.00 DC 0.00 AH 0.00

HANDLING CHARGE 0.00

TOT PUB CHG 12.74

SVC T/P USD 0.00 0.00 0.00 COD DGD

RS 0.50 SD 0.00 SP 0.00 PUB+HANDLING 12.74

ATTN: Product Service

PS 25018



