Remington Arms Co., Inc. Product Service Legal Case #:6718

Case Information

Incident Date **Date Opened** Date Opened(PS) Date Closed Pre Lit Obsolete RE# Lit 244266 10/21/2011 10/24/2011 10/24/2011

Customer Information City First Name Last Name Street Contact Type Business State Zip Age Reporter Mann & Son Mann & Son 515 W. Water St Pinckneyville 62274 Incident Samuel James Taylor 2239 East Manor Jackson 39211 H 601-594-2015

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4038 Could Not Duplicate Concern Unknown Concern: 1008 Fired on Bolt Closing S Fired when chambering a round

11/14/11 Per letter with rifle, on several occasions the gun has discharged during the act of chambering a round and without touching the trigger. Additionally the gun has fired while simply moving the safety to the fire position.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM Remington CF/BA 700/270 WIN n/a B6286409 XA 12/10/1980 Original Date Where Purchased Accessories Owner Purchased

SPORTS SOUTH SHREVEPORT

SCOPE BASE, BOTTOM HALF

LA

RINGS

U

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Settlement Date APV Date APV

Per Ilion, replace TPA, clean, test fire at BLSM program price

Repair/Replacement Repair/Replacement Cost

Date

42.40

11/14/2011

11/14/11 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean, test fire at BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|--------------|-----------------------------------|----------------------|
| | Examiner | | B.TRAVIS |
| | Exam Date | | 10/24/2011 |
| Examination | Product Type | | RF |
| • | Action Type | | A |
| | Assigned To | | T.NAGLE |
| Cause | 4006 | Altered Adjustments or Components | IMPROPER MAINTENENCE |
| | Description | · | 22" 270 WIN |
|) aal | Date Code | | XA |
| Barrel | Bore Plugged | False | |
| | Bulged | False |] |

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6718&Type=Case

.11/14/2011

| | Fired | False | |
|--------------------------|------------------------|----------------------------|------------------------------|
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| | Firing Pin | Slightly Worn; Functioning | <u> </u> |
| | Shroud | Slightly Worn; Functioning | |
| Bolt | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| | Condition | Slightly Worn; Functioning | |
| Extractor | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| | Block Condition | Select | |
| Locking | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | Select | · |
| | Exterior Condition | Slightly Worn; Functioning | |
| Overall | Stock Condition | Slightly Worn; Functioning | |
| 0 / 3. | Fore End Condition | Select | |
| | Condition | Slightly Worn; Functioning | |
| Receiver | Bulged | False | |
| | Description | | M/700 BOLT LOCK SAFETY |
| Safety | Function | Like new; Functioning | |
| | Sub-Assembly | Non-ISS | |
| | Lift | Select | .008 |
| Sear | Notch | Slightly Worn; Functioning | |
| | Tests | Test Fired | False |
| Feeding Test | Tests | False | |
| | Condition | Slightly Worn; Functioning | DIRTY.MIN TRIG RETURN |
| | Pull | Select | 2.5# |
| Trigger | Altered | True | SET SCREWS ALTERED |
| | Sub-Assembly | M/700 Bolt Lock | |
| Non-Remington Components | Description | | SCOPE BASE,BOTTOM HALF RINGS |

Samuel James Taylor 2239 East Manor Jackson, Mississippi 39211

6718

72" XA2/80 2.5%

October 11, 2011

Mann & Son Sporting Goods 515 W. Water St. Pinckneyville, IL 62274

Re. Remington Model 700

Please find enclosed Remington Model 700, Serial # 86286409 which I am sending to you for repair at the direction of Remington Arms Co. I purchased this gun new in the early 1980s and am its only owner and user.

On several occasions the gun has discharged during the act of chambering a round and without my touching the trigger. Additionally, the gun has fired while simply moving the safety to the fire position.

Per Remington's policy, I would appreciate your repairing or replacing the defective part(s). Should you have any questions please contact me at 601-594-2015.

Thank you.

Sam Taylor

B6286409

Model: フの(

RE00244266

could not duplicate concern.

T. A. Jirty + set screws Attend.

Aphace TPA, cleant Test Rine
under BLP Con A 20.00 + Ship

Quote

| DENIG DEPON # | | uate: | |
|----------------------------|-------------------|-------------------|-------|
| Mann & Son Sporting Goods, | 515 W. Water St., | Pinckneyville, IL | 62274 |

Remington. REMINGTON ARMS COMPANY, Inc.

| | | | JON, NEW Y | ORK 13357 | REMING | TON GUN | REPAIR IN | VOICE |
|------------------------|----------|------------------|--------------|--|---------------------------------|------------|--------------|-------|
| ngton Repair Facility | R. | Send to | 964 00.00 | Customer's Nar Street 22 City Jack | | | | |
| | | | IIIONI. | Telephone No | 6 | 01-59 | 4-20 | 15 |
| te Firearm Received | Date | Returned to Cus | tomer | Date Returned | | | Barrel Cod | e |
| 6-17-11 | | | | 10-17- | | | | |
| Gun Model | | Cal. or Ga | luge | Gra | de | 1 | Serial Numb | |
| 100 | | 270 | | | | 106 | 2864 | 07 |
| MINGTON GUNSMITH MA | LFUNCT | NON CODES FROM A | TTACHED CO | DE LIST | | | | |
| M 100 | | | | | | | · | |
| M295 | | | | | | | | |
| | escrib | e in detail | s cha | rges (o | ren | a ture | 4 | |
| Repairs Performed - Di | ascribe | e in detail | is cho | rges fo | rem | a ture | 4 | |
| | escribe | Part Name | | Retali Value | rem | | Arge Breakdo | own |
| Repaira Performed - Do | escribe | | | Retali | | | arge Breakdo | own |
| Repaira Performed - Do | escribe | | | Retali Value | Pans | | | 2 |
| Repaira Performed - Do | escribe | | | Retali Value | | | | 2 |
| Repaira Performed - Do | a scribe | | | Retali Value | Pans Labor | | | ssss |
| Repaira Performed - Do | escribe | | | Retali Value | Pans Labor Shippin | Repair Che | | 2 |
| Repaira Performed - Do | escribe | | | Retali Value | Pans Labor Shippin | Repair Che | | 2 |
| Repaira Performed - Do | escribe | | | Retali Value | Parts Labor Shippir Packin | Repair Che | | 2 |
| Repaira Performed - Do | escribe | | | Retali Value | Parts Labor Shippin Packin Ammo | Repair Che | | 2 |

Remington.

Repair Form
(NOTE: Please print and complete this form, and then include it with your firearm.)

| Model Number: 700 | Serial Number: B6286409 | | | | | |
|--|--|--|--|--|--|--|
| Name: SAN TAYLOR | Date of Purchase: EARLY 80'S | | | | | |
| Address (no PO Boxes): | Address (no PO Boxes): | | | | | |
| 2239 East MANDE De | 2ive | | | | | |
| city: Jackson | State: MS Zip: 39011 | | | | | |
| Phone (Daytime): 601-594-2015 | FEXT 601- 981- 4195 | | | | | |
| E-mail Address: staylor@ wealthviewcapital. com | | | | | | |
| Please describe your problem: | | | | | | |
| Dremature disch | rarae | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | - | | | | | |
| Additional Information: (Ammo type, | brand, handload specifications, etc.) | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| NOTE: Prior to shipping your firsam, provided and estimated repair time. | contact the Repair Canter for services. | | | | | |
| WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN THIS IS A VIOLATION OF FEDERAL LAW, IF YOU FEEL YOU SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WINNEER OF YOUR FIREARM. | Your firearm or in the same B CX with the firearm, Du must send spent shells please send them in a NTH ZIP CODE), Telephone and model and serial | | | | | |
| # Record the serial number of your firserm before ser a Pack your firserm for select and to prevent further ship in a firserm box. (Note: Original boxes may not Remove all accessories from your firserm to prevent Ship your INSURED firserm by either UPS or Parcel damage or loss during shipment, so you may elect to | damaga in shipping and haindling. Prafarably, : be returned.) t loss or damage. Post. Reminaton is not responsible for | | | | | |









