

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6574

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
240676	9/14/2011	9/15/2011	9/15/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Doug	Thompson	106 N 6 Mile Rd	Fort Gibson	OK	74434		H 918-731-9008 E Douglas.Thompson@eapac.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fired when releasing safety	Concern:1007 Fired on Safe Release		
C				

9/26/11 Per note with rifle, the rifle has fired when moving from safety to fire without pulling trigger.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6629849	AX	3/1/1973
Date Purchased	Where Purchased	Accessories	Original Owner			
	ANDERSON WHLSE CO MUSKOGEE OK		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, can offer to replace TPA, clean, test fire under BLSM program price						

Repair/Replacement Cost	Repair/Replacement Date
42.40	9/26/2011

9/26/11 Per Ilion, could not duplicate concern. Trigger assm dirty and sticky. Can offer to replace TPA, clean, test fire under BLSM program price of \$20 + shipping and tax.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/15/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		AX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

22"  
AX37?  
4th  
005

6574

Model Number: <b>700</b>		Serial Number: <b>6629849</b>	
Name: <b>Doug Thompson</b>		Date of Purchase: <b>1970'S DON'T KNOW</b>	
Address (no PO Boxes): <b>106 N. 6 MILE RD.</b>			
City: <b>FT GIBSON</b>	State: <b>OK</b>	Zip: <b>74434</b>	
Phone (Daytime): <b>918-891-9009</b>		Fax:	
E-mail Address: <b>DOUGLAS.THOMPSON@EAPAC.COM</b>			
Please describe your problem:			
<p><b>THE RIFLE HAS FIRED WHEN MOVING FROM SAFETY TO FIRE WITHOUT PULLING TRIGGER</b></p> <p>could not duplicate concern. T.A. dirty + sticky. can offer to replace TRA, clean + test Remunden BLP Ron @ 20.00 + Ship Quote</p> <p>500 characters left</p>			
<p><b>NOTE:</b> Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.</p>			

6629849

Model: 700



RE00240676

OR SPENT SHELLS IN YOUR  
WITH THE FIREARM. **THIS IS A**  
YOU FEEL YOU MUST SEND SPENT  
SEPARATE PACKAGE AND INCLUDE  
, TELEPHONE AND MODEL AND  
YOUR FIREARM.

your firearm before sending it.  
event further damage in shipping and  
ably, ship in a

firearm box. (Note: Original boxes may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset

RECEIVED  
SEP 20 2011

BY: .....







