

Remington Arms Co., Inc.
Product Service
Legal Case #:6428

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
237273	8/5/2011	8/8/2011	8/8/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		John	Tikkaneu	14371 Korhouen Rd	Baraga	MI	49908		H 906-201-1134
Reporter	Wilkinsons Store		Wilkinsons Stor	117 Superior Ave	Baraga	MI	49908		W 906-353-6257

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	gun will go off	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

8/10/11 Per letter with rifle, gun will not fire at times. Trigger acts like safety is on. Then when you least expect it the gun will go off. Now firing pin will not reset.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	25767	B6543703	BE	1/1/1984
Date Purchased	Where Purchased	Accessories	Original Owner			
	K MART ENTERPRISES SHAKOPEE MN		U			

CONCERN:NOT FIRING AT TIMES,DELAYED FIRING

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, can offer to replace TPA, clean, test fire at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

8/10/11 Per Ilion, trigger assm dirty, set screws altered, trigger not returning properly. Can offer to replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/8/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 243 WIN
	Date Code		BE
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

Gun will Not Fire AT
Times. Trigger Acts Like
Safety on. Then when
you least expect it, The
Gun will Go OFF.
Now firing Pin will Not
reset.

6428

22"
BEI/84
2.5#
1011

owner - Questions please call

Name: John Tikkanen
14371 Korhonen RD
Baraga, MI 49908

Phone: 906-261-1134

Remington Arms
ATTN: Repairs/SMF
14 Hoefler Ave
Bacon N.Y 13357

RECEIVED
AUG 09 2011
BY:.....

B6543703

Model: 700



RE00237273

T.A. dirty, set screws
Altered, Trigger not returning
properly. Can offer to replace
TPA, clean + test fire at 1/2
normal cost.

Quote









