

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7095

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
250471	12/15/2011	12/16/2011	12/16/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Vermont Field Sports		Vermont Field S	1458 Rt 7 South	Middlebury	VT	05753		W 802-388-3572

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Fired on bolt closing Concern:1008 Fired on Bolt Closing		Unknown	
C				

1/11/12 Per note with rifle, gun went off when shutting bolt by itself and pulled the trigger and gun didn't go off. He moved the bolt and the gun went off without pulling the trigger.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	A6770939	BA	1/1/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE BASE	U			

CONCERN: FBO

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				

1/11/12 Per Ilion, could not duplicate concern. Rifle has an extreme max headspace condition. Needs a new over size bolt. Replace TPA, clean and test fire at BLSM program price.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/16/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		BA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while		

	Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Worn; Functioning	HAS A MAX HEADSPACE COND. WILL NEED AN OVERSIZED BOLT TO CORRECT
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,SOME RUSTING
	Pull	---Select---	4#
	Altered	True	PULL SCREW ADJUSTED
Non-Remington Components	Description		TWO PIECE BASE

VERMONT FIELD SPORTS  
1458 Rte. 7 South  
Middlebury, VT 05753  
(802) 388-3572

7095

FFL 603001011K33993

22"  
SA 1/28  
4#

could not duplicate concern. Old  
Rifle has AN EXTREME WAX HEAD  
SPACE CONDITION. Needs A NEW OVER  
SIZE BOLT. Replace at 1/2 cost.  
T.A. Daily & pulls screw at head  
replace TPA, clean & TEST RIF  
under BCP for \$20. + ship

Quote

David Hanson

802 989-3626

PO BOX 176 Shoreham  
VT 05770

gun went off when  
shot the Bolt By its  
Self and ~~shot~~ pulled trigger  
gun didnt go off moved  
Bolt gun went off with  
out pulled trigger

RECEIVED  
DEC 20 2011

BY:.....

A6770939  
Model: 700



RE00250471

Serial Number:

Please make This guy happy he  
is A good customer of The Shop.  
E-mail me to keep me Abreast of The  
Progress of The Repair.

E-mail VT Field Sports @ ~~myfairpoint~~  
MYFAIRPOINT.NET

Thanks Gores Manager VFS

# Quotation

Remington Service

PO Box 700

Madison, NC 27025-0700

# Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

**ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS**

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

**Repair Number** RE00250471  
**Serial Number / Description** A6770939  
 Model 700 Center Fire Caliber: 270 WIN

**Date Received:** 12/15/2011  
**Estimate Date:** 12/16/2011  
**Date Printed:** 01/11/2012

**Customer:**  
 VERMONT FIELD SPORTS  
 1458 RTE SOUTH  
 MIDDLEBURY, VT 05753 US

**Return To:**  
 VERMONT FIELD SPORTS  
 1458 RTE SOUTH  
 MIDDLEBURY, VT 05753 US

Please Circle One:

VISA MC DISCOVER Card No. \_\_\_\_\_ Exp.Date \_\_\_\_\_  
 Open Account: R \_\_\_\_\_ PO Number: \_\_\_\_\_

Approval Signature: \_\_\_\_\_ Date: \_\_\_\_\_  
 Daytime Phone: (\_\_\_\_) \_\_\_\_\_ Time to Call: \_\_\_\_\_

☐ If you desire any change, please use the reverse side for your comments and mark this box.

Problems	
Reported	Found
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION	M112 - HEADSPACE IS EXCESSIVE M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

**Technician Comments**  
 could not duplicate concern.rifle has an extreme max headspace condition,needs an over sized bolt to correct.trigger assm dirty, trigger pull screw al  
 tered.replace trigger plate assm,clear and test fire under bolt lock program for \$20.00 + shipping

ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)								
Material	Type	Description	Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLACK (OS)	1	Warranty	1	.00	0	.00
F92897	Part	700 BOLT ASSB BDL MAX LONG F1	1	Billable	1	135.00	50	67.50
F93712	Part	700 EXTRACTOR REG (7400;710)	1	Billable	1	12.00	50	6.00
4000114	Service	GR-SHIPING & HANDLING (GUN REPAIR)	1	Billable	1	17.00	0	17.00
4000116	Service	GR-LABOR	20	Billable	20	1.00	0	20.00
4000119	Service	GR-TEST	1	Warranty	1	.00	0	.00

**Sub Total:** 110.50  
**Est Sales Tax:** 3.68

*Total: 114.18*











