Remington Arms Co., Inc. Product Service Legal Case #:6787

Case Information

Date Opened RE# Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete Lit 11/2/2011 11/28/2011 11/29/2011 248153

Customer Information

Last Name Street Contact Type Business First Name City State Zip 16106 Bowling Dr. H 606-739-4586 Incident Rodney Viars Catlettsburg 41129

Incident Information

Claims Codes Repair Est. **Medical Status** Medical Treatment

ΡI

PD Cause: 4006 Altered Adjustments or Components Unknown S

Concern: 1008 Fired on Bolt Closing

C FBC

11/2/11: Customer called in. He stated he bought gun 2nd hand & it has a hair trigger. He had a FBC while hunting back in the spring. No damage, No injury. df

Firearm Information

Model/Ga. SKU DOM Mfg. Type Serial Bbl. Remington CF/BA 700/243 WIN n/a A6314371 ΕI 10/1/1976

Original Owner Date Purchased Where Purchased Accessories

OUTDOOR SPORTS DAYTON OH N

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion - Quote to repair under BLM

Repair/Replacement Repair/Replacement Cost Date \$30.40 12/12/2011

11/2/11: Mailing ARS & forms. Box order# 1267762. df 12/12/11: Per Ilion - TA set screws altered, trigger not returning properly. Trigger clearance min. to guard. Replace TA, clean & test fire under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/29/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 243 WIN
	Date Code		EI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while		

	Obstructed	i	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Bolt  Extractor  Locking  Overall  Receiver  Safety  Sear  Feeding Test  Trigger	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Extractor  Locking  Overall  Receiver  Safety  Sear  Feeding Test	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Crown Slightly Worn; Functioning False On Each Slightly Worn; Functioning False On Each Slightly Worn; Functioning False On Slightly Worn; Functioning False On Slightly Worn; Functioning False Slightly Worn; Not Functioning GUARD.WILL FOLLOW DOWN.MARKS ON TRIG FROM A Select	
	Sub-Assembly	Non-ISS	
Locking  Overall  Receiver  Safety  Sear	Lift	Select	.007
Sear	Notch		
		Test Fired	False
	Tests	False	
	Condition		TRIG NOT RETURNING,MIN CLEARANCE BETWEEN TRIG AND GUARD.WILL FOLLOW DOWN.MARKS ON TRIG FROM A TRIG
Trigger	Pull	Select	2#
Irigger	Altered	True	SET SCREQWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	



6787

November 2, 2011

Rodney Viars 16106 Bowling Dr. Catlettsburg, KY 41129 Phone: 606-739-4586

Ref: #6787, Model 700, Serial # A6314371

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure



T.A. Set Screws Altered, Trig. Not ordurang property. Trig. charace min to Guard. Aphan TPA, cleant trest fire under Dep for & 20.00+ Ship Quole

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

## Service Request

## Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00002693

Serial Number / Description

A6314371

Model 700 Center Fire Caliber: 243

Customer: RODNEY VIARS 16106 BOWLING DR

Email:

CATLETTSBURG, KY 41129 US

Date of Request:

11/02/2011

Date Printed:

11/02/2011

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section ...

Product Service # 6787 - FBC

Parts And Service Details

Material

Type

Description

Qty Needed Warranty

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00 .00

## ARS LABEL REQUEST FORM

Service Request #

11/02/2011

**RETURN ITEM TO:** 

DATE:

QUANTITY:	1		WEIGHT PER PACKAGE:	10 LBS				
REQUESTED BY: fulcherdm			email address: I WILL I					
Business:		Remington Servi PO Box 700 Madison, NC 27 www.Remington	7025-0700					
LABEL INFORMATION								
MAIL LABE	L TO:	RODNEY VIAR 16106 BOWLIN CATLETTSBUF SR00002693						

Email:

ILN

Arms Services



4XXE SVC	GNDCOM				WΤ	10.0	CURR LBS	USD	1	OF	1
TRAC	KING# 1 1:SR000		690	67991	665						
REF		02033									

SR00002693

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD

DV 0.00 COD 0.00 RS 0.50

DC 0.00 DGD 0.00 SD 0.00

DC 0.00 PR 0.00 SP 0.00

TOT PUB CHG 9.04 PUB+HANDLING 9.04









