Remington Arms Co., Inc. Product Service Legal Case #:7108

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 250888 12/16/2011 12/19/2011 12/19/2011

Customer Information

Zip Type **Business** First Name Last Name Street City State Contact

Wisman 11 Randi Rd PA 17025 Incident George Enola

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern Unknown gun on safe and fired when unloading Concern:1005 Unexplained Discharge Safe ON

1/13/12 Per note with rifle, gun was on safe and went off when he started to unload.cm

Firearm Information

Mfg. Type Model/Ga. SKU Bbl. DOM CF/BA 700/270 WIN n/a 6596842 RE 11/1/1972 Remington

Date Purchased Where Purchased Accessories **Original Owner**

JERRYS SPORT OLYPHANT PA

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Date Cash Date Cash Settlement Release of Claims Release Date Reimbursement Settlement

Replace TPA, clean and test fire at BLSM program price

Repair/Replacement Repair/Replacement Cost Date 30.40 1/13/2012

1/13/12 Per Ilion, could not duplicate concern. Trigger assm set screws altered. Replace TPA, clean and test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		12/19/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		RW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7108&Type=Case

1/13/2012

	Shroud	Slightly Worn; Functioning	
Bolt Extractor Locking	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	<u> </u>
	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	· ·
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.004
	Notch	Slightly Worn; Functioning	
	AT .	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

 w^{il} 2W14 44 .00

Service Request Number

GEORGE WISMAN

ENOLA, PA 17025 US

11 RANDI ROAD

Serial Number / Description

SR00005933

6596842

Date of Request:

Date

12/06/2011

Printed: 12/06/2011

Customer:

Destination:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed

COUld Not Suphism to concern the T.A. Set screws altered hiphace TRA clear test fine and ex BCP for to 20. + 5 hrs Quot

Reason For Retur

M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

// Service Request Section 🛬 🐇

ARS Sent. 12/6 drs



GUN, WAS ON SAFE AND WENT OFF

WYEN I STARTED

to UNLOAD

Marge Wissman

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax:

.00 .00

Grand Total:

\$.00







