Remington Arms Co., Inc. Product Service Legal Case #:6625

Case Information

RE# Date Opened

Date Opened(PS)

**Date Closed** 

**Incident Date** 

Pre Lit Lit Obsolete

9/28/2011

**Customer Information** 

Type Business First Name Last Name

Street

City State Zip Age

Contact

Incident

Gordon

7007 Misty Ridge Dr. Converse TX 78109

H 210-887-6464 E sgtgtwood@yahoo.com

Incident Information

Claims

Codes

Wood

Repair Est.

**Medical Treatment** 

**Medical Status** 

PΙ

PD

Cause:4079 Other - Unexamined

Unknown

S

Concern: 1008 Fired on Bolt Closing

. Un

C FBC

Customer sent an email through Right Now Tech. Ref # 110919-000282. He stated that he has a Model 700 in .223 & he had fired it & then when he chambered another round the rifle fired again without pulling the trigger. No damage, No injury. df

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial

Bbl. DOM

Remington

CF/BA

700/223 REM

20000

G281332

DI. DUN

Date Purchased

Where Purchased

Accessories

Original Owner

U

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date APV

Date Cash Date

APV

Repair/Replacement

Repair/Replacement

Cost

Date

9/28/11: Mailing ARS, letter, form. df

Examination[Remington/CF/BA]

Part Sub-Part

Code

Comment

Reference # 110919-000282

Status Updated

Assigned To Administrators

Dell -

Product Firearms

Centerfire Rifles

Not specified

Queue

CSR

Date Created 09/19/2011 04:54 PM

Date Initial Solution Response 09/22/2011 02:27 PM

Last Updated 09/24/2011 05:26 PM

Customer SmartSense +1 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

## Model 700 Misfire

#### **Discussion Thread**

#### Customer (Gordon Wood)

09/24/2011 05:26 PM

Dell: This rifle is a Remington Model 700, SN G281332 in .223 Rem. Address: 7007 Misty Ridge Drive, Converse TX 78109. My day time phone number is 210-887-6464. Thanks. Gordon Wood

From: Remington Information

To: sqtqtwood@yahoo.com

Sent: Thursday, September 22, 2011 1:27 PM

Subject: Model 700 Misfire [Incident: 110919-000282]

#### Response (Dell -)

Dear Mr. Wood,

09/22/2011 02:27 PM

We would like to have the firearm come into our Product Services Department at our factory for examination. Please reply back to me with the serial number of the firearm, caliber, your mailing address and phone number. We would like to send you a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that you can fill out to let the examiner know exactly what happened and when this occurred.

Sincerely,

### Note (Jennifer Rakestraw)

09/21/2011 05:50 PM

Emailed Dell & Christy so they can reassign this to them since it fired on consumer when he was chambering the round.

#### Customer (Gordon Wood)

09/19/2011 04:54 PM

I have a model 700 in 223 that I had fired and when I chambered another round the weaponed fired again without pulling the trigger. The weapon was pointed in a safe direction so there was no danger but what can I do to identify the problem or keep this from happening again?

Thanks

## **Primary Contact**

First Name: Gordon Last Name: Wood Organization:

> Login: sgtgtwood Title:

Contact Type:

Email: sgtgtwood@yahoo.com

Email - Alternate #1:

Email - Alternate #2:

Office Phone: Mobile Phone:

Fax:

Assistant Phone:

Home Phone:

Street

City

State/Province Postal Code

Country

Additional Information



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:		9/28/2011	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
PUPASE CHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX Translation of Association (Association of Association (Association of Association of Association of Association (Association of Association of Association of Association of Association of Association of Association (Association of Association of Associa
DESCRIPTION:	Ref# 6625 rifle			

## LABEL INFORMATION

MAIL LABEL TO: Gordon Wood

7007 Misty Ridge Dr. Converse, TX 78109 Phone: 210-887-6464

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

## PLEASE COMPLETE ALL PARTS OF THIS FORM, AND SEND TO THE MEDIA CCORDINATOR

4XX596 SEP 28, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM ACT UT 10.0 LBS
TRACKING# 1Z4XX5969067737985
REF 1:GORDON WOOD/CD/DMF
REF 2:REF#6625/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00

AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 11.53 PUB+HANDLING 11.5