

Remington Arms Co., Inc.
Product Service
Legal Case #:6681

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
243283	10/13/2011	10/14/2011	10/14/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Ross	Yates	213 Ridge Rd	Mayodan	NC	27027		H 336-548-9049

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Go will go off by itself			

Customer sent gun in w/our repair form. He stated that gun will go off by itself. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	A6899357	AA	3/23/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	K MART FAIRLESS HILLS PA		N			

CONCERN:GOES OFF BY ITSELF

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	10/26/2011				

10/26/11: Per Ilion - Could not duplicate concern. TA dirty. Replace TA, clean & test fire under BLM - quote. Customer apprvd quote & paid by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/14/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		AA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	DENTS,SCRATCHES
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	7#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

6681

Remington.

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

22"
AA3/80
7#
100?

Model Number: 700 Serial Number: A6899357

Are you the original owner? ☐ YES ☒ NO

Name: ROSS L YATES Date of Purchase:

Address (no PO Boxes):

213 RIDGE RD

City: MAYODAN State: N.C. Zip: 27027

Phone (Daytime): 336548 9049 Fax:

E-mail Address:

☐ I would like to receive future e-mail updates from Remington.

Please describe your problem:

GUN WILL GO OFF
BY IT SELF

Ammunition Information:

Manufacturer: WINCHESTER Type: 270 130gM

Other (i.e. bullet weight/type, shot size, powder):

Handload Information:

Powder Used:

Powder Weight:

Primer Used:

Reloader Used:

and Lubrication):

ed: BUTERS, GUN, SLICK NITRO SOLIDEN

ore? (Months or Number of rounds) 2 TIMES / YEAR 3 POUNDS

action? (Months or Number of rounds) 11

trigger assembly? (Months or Number of rounds) 11

Brand of lubricant used: REMINGTON REM OIL TEFLON

RECEIVED
OCT 19 2011

BY: _____

could not duplicate concern
T.A. dirty. Replace TPA, clean
+ test fire under B&P Cor
X 20.00 + ship

Quote





