Remington Arms Co., Inc. Product Service Legal Case #:6316

Case Information

Date Opened(PS) **Date Closed Incident Date** Obsolete RE# **Date Opened** 7/15/2011 6/29/2011 7/18/2011 235733

Customer Information

Business First Name Last Name Street City Zip Age Contact Type 108 Wright Bend Rd Phillip Adcock Smithville W 615-597-4196 Reporter Belk Sporting Goods

Incident Information

Repair Est. Medical Treatment Medical Status Claims Codes

PI

Cause:4038 Could Not Duplicate Concern PD Unknown Concern:1006 Unexplained Discharge Safe OFF

Fired without pulling trigger

7/1/11 Per call from Adcock, his customer brought in a 700 SPS Var 22-250. He said he had shot it, bolted it loaded, didn't put the safety on and laid it down and it fired on it's own.cm

Firearm Information

Model/Ga. SKU Вы. DOM Mfg. Type CF/BA 700/22-250 REM 84216 G6744959 CC 4/4/2008 3:49:00 PM Remington Original Owner

Date Purchased 5/2/2008

Where Purchased

Accessories

JERRY S - BONITZ BROTHERS TWO PIECE BASE Y

CONCERN: FIRED WITHOUT PULLING TRIGGER

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Date Settlement Date APV APV

Per Ilion, to restore confidence will replace TPA, clean, test at n/c

Repair/Replacement Repair/Replacement Date Cost

47.40 7/20/2011

7/1/11 Mailing ARS to dealer.cm 7/20/11 Per Ilion, could not duplicate concern. To restore confidence in rifle will replace TPA, clean, test at n/c.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date	'	7/18/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 22-250 REM HB
	Date Code		CC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		-

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6316&Type=Case

7/20/2011

	1	<u> </u>	_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
•	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn, Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	<u></u>
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	7
	Exterior Condition	Slightly Worn; Functioning	RUST ON BBL AND REC UNDER STK
Overall	Stock Condition	Slightly Worn; Functioning	SOME MARS, DENTS
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	1
Receiver	Bulged	False	
	Description	1	XMP SAFETY \
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	†
	Lift	Select	[.007
Sear	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	1
	Pull	Select	5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	· ·
Non-Remington Components	Description	1	TWO PIECE BASE

Remington

26" CC4/08

6316

June 29, 2011

Phillip Adcock
Belk Sporting Goods
108 Wright Bend Rd
Smithville, TN 37166

Subject: Case #6316, Model 700


Dear Mr. Adcock,

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



RE00235733

to justone confidence in Rife
will replace TPA, clearly Test
and replace TPA, clearly Test

23045

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

	<u> </u>
Model Number: 700	Serial Number: 66744959
Are you the original owner?: YES NO	
Name: Lee foy Barretto	Date of Purchase: 5-2-08
Address (no PO Boxes): 6727 Francis F	serry fel.
City: Rock Island	State: 7N Zip: 38581
Phone (Daytime): 931- 686-8361	Fax:
E-mail Address:(if e-mail address is provided, notification sent)	of receipt and shipment will be
E-mail Address:	
Γ I would like to receive future e-mail updates from Re	mington.
Please describe your problem and date of occurrence	
of Went of With Trisser could come Said to	eloaded + Layed Down of pulling ustoner Service + Qot Auch Phillip
Ammunition Information:	
Manufacturer: Hornady	Type: 22.250
Other (i.e. bullet weight/type, shot size, powder):	5591.
Handload Information: None	
Powder Used:	Powder Weight:
Case/Huil Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	6/29	/2011 REQUESTED BY:	christy	
QUANTITY:	1	WEIGHT PER PACKA	GE:	10
RTEASE CHECKONES MEDIA	· .			
COORDINATOR			XXX	
TO MAIL		I WILL MAIL		
DESCRIPTION:				
·	•	700	•	
,		·		

LABEL INFORMATION

MAIL LABEL TO:	Phillip Adcock Belk Sptg Goods 108 Wright Bend Rd Smithville, TN 37166 615-597-4196	
RETURN ITEM TO	Rem Prod Serv Case # 6316	

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX595 JUN 30, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969066045680 REF 1:BELK SPT GDS/PHILLIP A/CD/CM REF 2:700/CASE#6316

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 0.00 PR SP 0.00 TOT PUB CHG 9.70 PUB+HANDLING 9.70

