Remington Arms Co., Inc. Product Service Legal Case #:6475

Case Information **Date Closed** RE# **Date Opened** Date Opened(PS) **Incident Date** Pre Lit Obsolete 8/22/2011 8/22/2011 237939 8/15/2011 **Customer Information** Street City Zip Contact First Name Last Name State Age Type Business H 405-306-4814 2400 Sand Plum Dr Zachary Cruse Edmond OK 73025 Incident E zcruse@uco.edu Incident Information Medical Repair Medical Codes Claims Treatment Status 9 Est. ΡI Other - Unspecified or Undetermined -PD Cause:4040 Firearms Unknown Fires on both safe and S Concern: 1028 Fired With Safe ON fire C 8/30/11 Per note with rifle, gun fires on both "safe" and "fire".cm Firearm Information SKU Serial Bbl. DOM Model/Ga. Mfg. Type 84013 EB 10/26/2007 7:39:14 AM Remington CF/BA 700/270 WSM S6631560 **Original Owner Date Purchased** Where Purchased Accessories RSR GROUP TEXAS, INC. U 12/14/2007 CONCERN: FIRES ON SAFE Ammunition Information Mfg. Type Cal./Ga. SKU UPC **DOM** Mfg. Code

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reload

N

Factory

Y

Settlement Release of Claims Release Date

Silvertip /130

Other

Cash Reim. Date Cash Date Reimbursement Settlement APV APV

Per Ilion, replace TPA, clean, test fire at no charge

Winchester

Concern

0:

Repair/Replacement Repair/Replacement Cost

Date

47.26

8/30/2011

8/30/11 Per note with rifle, trigger assm and action has a sticky lube residue. Excessive trigger over travel. Replace TPA, clean, test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
Examination	Exam Date		8/22/2011	
	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	11411 1411 1		UNABLE TO DETERMINE IF BLOCKER SCREW HAS BEEN ALTERED	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6475&Type=Case

8/30/2011

	Description		24" 270 WSM FL
Barrel	Date Code	7	EB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	· ·
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
e.	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	-
<u> </u>	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	\ \
	Description		XMP SAFETY
Safety	Function	Like new; Not Functioning	
·	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	EXSESSIVE OVER TRAVEL
Trigger	Pull	Select	5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Factory Repair Instructions
(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700CDL-SF	Serial Number: S6631560						
Are you the original owner?:							
Name: Zachary Cruse	Date of Purchase: 12/14/2007						
Address (no PO Boxes): 2400 Sand Plum Drive							
City: Edmond	State: OK	Zip: 73025					
Phone (Daytime): (405) 306-4814	Fax: N/A						
E-mail Address: zcruse@uco.edu I would like to receive future e-mail updates from Remington.							
Please describe your problem:							
Gun fires on both "safe" and	"fire"						
T.A. HACT. WAS A ST	Icky lube resi	idue.					
Excessive Trig. ou							
TPA, clean + Tet	River At 14/	C					
#23014	_						
	and the second s						
Ammunition Information:							
	Type: Ballistic Sil						
Other (i.e. bullet weight/type, shot size, powder): 13	0 gr	*:					
Handload Information:	L						
Powder Used: IMR4350	Powder Weight: 58.8						
Case/Hull Used: Winchester	Primer Used: CCI #25(
Bullet Type/Shot Size: 130 gr. Hornady Reloader Used: Hornady Lock-n-Load AP Interlock H2730							
	4/30						
Firearms Care (Cleaning and Lubrication):							
Brand of cleaning solution used: Hoppes							
How often do you clean the bore? (Months or Number of rounds) Approx. every 50 rounds							
How often do you clean the action? (Months or Number of	NDDION: CVC.	ry 50 rounds					
How often do you clean the trigger assembly? (Months or	- ItALEI	mal only - approx. cy 50 rounds					
Brand of lubricant used: Remoil		SECETIVE"					
		LL AUG 2 6 2011 L					

PS 25392

How often do you lubricate the bore? (Months or Number of rounds) every time cleaned gun

How often do you lubricate the action? (Months of Number of rounds) every time cleaned gun

How often do you lubricate the trigger assembly? (Months or Number of rounds) every time cleaned gut

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

「x」。 YES

NC

Comments:

Gun has been fired at most 200 rounds

7.9

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? Never

What were the services performed? Only service ever performed on gun was scope mount

Ship your INSURED firearm by either UPS or Parcel Post to:

REMINGTON ARMS CO., INC

ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE THE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND

S6631560 Model: 700



KE00237939

ling it.

mage in shipping and handling. Preferably,

de returned.)

oss or damage.

de the box. Shipments without a proper-

purchase insurance from your carrier.

idelines:...

med to you C.O.D. (To avoid C.O.D. Charges, please

include your credit card number and expiration gate with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.







