

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6858

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 246995 | 11/15/2011  | 11/16/2011      | 11/16/2011  |               |         |     |          |

## Customer Information

| Type     | Business             | First Name | Last Name      | Street               | City     | State | Zip   | Age | Contact        |
|----------|----------------------|------------|----------------|----------------------|----------|-------|-------|-----|----------------|
| Reporter | Dicks Sporting Goods | ---        | Dicks Sporting | 5550 WHITTLESEY BLVD | Columbus | GA    | 31909 |     | W 706-320-0179 |

## Incident Information

| Claims | Codes        | Repair Est.                 | Medical Treatment | Medical Status |
|--------|--------------|-----------------------------|-------------------|----------------|
| PI     |              |                             |                   |                |
| PD     | Cause:4038   | Could Not Duplicate Concern |                   |                |
| S      | Concern:1007 | Fired on Safe Release       | Unknown           |                |
| C      | FSR          |                             |                   |                |

Dealer sent rifle in without note. Factory called & dealer stated that rifle had FSR. df

## Firearm Information

| Mfg.           | Type                      | Model/Ga.     | SKU            | Serial   | Bbl. | DOM                  |
|----------------|---------------------------|---------------|----------------|----------|------|----------------------|
| Remington      | CF/BA                     | 700/3006 SPRG | 85536          | G7003547 | DE   | 9/7/2010 11:19:18 AM |
| Date Purchased | Where Purchased           | Accessories   | Original Owner |          |      |                      |
|                | DICK S SPORTING GOODS/ATL |               | U              |          |      |                      |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

| Settlement                        | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-----------------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Per Ilion - Repair under warranty |                         |                         |               |                 |                |               |
|                                   | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                                   | \$52.88                 | 12/5/2011               |               |                 |                |               |

Per Ilion - Could not duplicate concern. TA functions as designed. To restore confidence in rifle, will fit a new TA, check over & test fire @ n/c - warranty. df

## Examination[Remington/CF/BA]

| Part        | Sub-Part               | Code                        | Comment       |
|-------------|------------------------|-----------------------------|---------------|
| Examination | Examiner               |                             | B.TRAVIS      |
|             | Exam Date              |                             | 11/16/2011    |
|             | Product Type           |                             | RF            |
|             | Action Type            |                             | A.            |
|             | Assigned To            |                             | T.NAGLE       |
| Cause       | 4038                   | Could Not Duplicate Concern |               |
| Barrel      | Description            |                             | 24" 3006 SPRG |
|             | Date Code              |                             | DE            |
|             | Bore Plugged           | False                       |               |
|             | Bulged                 | False                       |               |
|             | Fired                  | False                       |               |
|             | Fired while Obstructed |                             |               |
|             | Muzzle/Crown Condition | Slightly Worn; Functioning  |               |

|              |                    |                            |            |
|--------------|--------------------|----------------------------|------------|
| Bolt         | Firing Pin         | Like new; Functioning      |            |
|              | Shroud             | Like new; Functioning      |            |
|              | Face               | Like new; Functioning      |            |
|              | Handle             | Like new; Functioning      |            |
|              | Stop               | Like new; Functioning      |            |
| Extractor    | Condition          | Slightly Worn; Functioning |            |
|              | Cut Condition      | Like new; Functioning      |            |
|              | Ext/Eject Test     | False                      |            |
| Locking      | Block Condition    | ---Select---               |            |
|              | Lug Condition      | Slightly Worn; Functioning |            |
|              | Notch Condition    | ---Select---               |            |
| Overall      | Exterior Condition | Like new; Functioning      |            |
|              | Stock Condition    | Like new; Functioning      |            |
|              | Fore End Condition | ---Select---               |            |
| Receiver     | Condition          | Like new; Functioning      |            |
|              | Bulged             | False                      |            |
| Safety       | Description        |                            | XMP SAFETY |
|              | Function           | Like new; Functioning      |            |
|              | Sub-Assembly       | Non-ISS                    |            |
| Sear         | Lift               | ---Select---               | .011       |
|              | Notch              | Like new; Functioning      |            |
|              | Tests              | Test Fired                 | False      |
| Feeding Test |                    | False                      |            |
| Trigger      | Condition          | Like new; Functioning      |            |
|              | Pull               | ---Select---               | 2.5#       |
|              | Altered            | False                      |            |
|              | Sub-Assembly       | X-Mark Pro                 |            |

Kelly, Shannon L.

From: Schults, Colleen M.  
Sent: Monday, November 14, 2011 4:16 PM  
To: Kelly, Shannon L.  
Subject: RE246995

Hey Shannon,

Can you call Dicks Sporting Goods in Columbus GA for the above repair it is a Model 700 30-06 SPRG camo.  
We need to know what is wrong with it.

Thanks,

Colleen

STORE 325  
(678) 817-0676  
DICK'S SPORT GOODS 325  
5550 WHITTLESLEY BLVD  
COLUMBUS GA 31909

~~678-817-0676~~  
700-320-0179

Serial  
Number:

G7003547

Model: 700



RE00246995

RECEIVED  
NOV 21 2011

BY:.....

discharged  
when safety  
released

could not duplicate concern  
T.A. functions as designed. TO  
restore confidence in rifle will  
fit a NEW TPA, check over + TEST  
Rifle at N/C

unmanky







