

Remington Arms Co., Inc.
Product Service
Legal Case #:5909

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
236915	7/29/2011	2/21/2011	8/1/2011	2/18/2011			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Ed/Clava	Gray	100 Lillian Dr.	Sitka	AK	99835		H 907-738-2672 C 907-738-7880 E clavgray@hotmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

2/21/11: Customer called in & stated that his wife was shooting the rifle on 2/18/11 and as the rifle was on the shooting bench she experienced a FBC. No damage, No injury. He stated the rifle was purchased used. He stated he heard we were having issues with the M/700 & may not want this one back. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/223 REM	85362	G6652686	AB	4/2/2007 6:09:36 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	CABELA S INC/WAREHOUSE	TWO PIECE BASE	N			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$47.40	8/5/2011				

2/21/11: Sending letter & form. df 8/5/11: Per Ilion - Could not duplicate concern. To restore confidence in rifle - will replace TA, clean & test fire at n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/1/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		20" 223 REM
	Date Code		AB
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.006
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE

5909

7-6-11

This Rifle WAS purchased
from Cabalis gun Room.

20"
AB3/07
3.5"
.006

I T shot very irratically
Dented 2 Primers

After 40 Shots it discharged

When the bolt WAS Closed.

This WAS purchased for my

8 year OLD SON.

RECEIVED
AUG 04 2011

BY:.....

CLARA GRAY
100 Lillian Dr.
SITKA AK. 99835

907 738 7880

Clairgray @ hotmail.com
could not duplicate concern.

To restore confidence in rifle
will replace TPA, clean + test fire

BT A/C

#230145

G6652686

Model: 700



RE00236915

Number:
TATJAC







