

Remington Arms Co., Inc.
Product Service
Legal Case #:6517

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
239353	8/29/2011	8/30/2011	8/30/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		John W	Harper	1125 Military Rd	Mount Vernon	AL	36560		H 251-331-2229 E mtvernonhardware@bellsouth.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired without touching trigger	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

9/9/11 Per letter with rifle, after firing 1st bullet from gun, the next bullets lead will smash at tip when bolted in. Secondly, raised gun to prepare for shot, gun has fired without touching trigger. This has occurred 2 times.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	27121	G6767445	OC	7/24/2008 11:33:36 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACADEMY CORP		U			

CONCERN: FIRES WITHOUT TOUCHING TRIGGER

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, to restore confidence in rifle will fit new TPA, clean and repair as needed at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				

9/9/11 Per Ilion, could not duplicate concern with trigger assm to restore confidence in rifle will fit new TPA, clean and repair as needed at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/30/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 270 WIN
	Date Code		OC
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

6517

August 19, 2011

Remington Repair

Owner- John W. Harper

1125 Military Rd.

Mt. Vernon, AL 36560

telephone- 251-331-2229 (Bonnie) 251-829-9418

e-mail - mtvernonhardware@bellsouth.net

Model- # 700 Serial# G6767445

- Owner has owned & used guns for 40 years. Owns multiple rifles.

① After firing 1st bullet from gun the next bullets lead will smash (at tip) when bolted in.

② Raised gun to prepare for shot, gun has fired with-out touching trigger. This has occurred 2 times.

If there is a problem or no corrective action that can be taken by your department Please telephone / email me so we may discuss my options or upgrades.

RECEIVED
SEP 06 2011

BY:.....

Serial
Number:

G6767445

Model: 700



RE00239353

24"
00 7/08
5#
011

for. At 11:00 AM 10/10/08 - 10:00 AM

PHM 10/10/08 10:00 AM - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM

could not duplicate concern

for. At 11:00 AM 10/10/08 - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM

again as needed at N/C 10/10/08

at 10:00 AM 10/10/08 - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM

at 10:00 AM 10/10/08 - 10:00 AM





