

Remington Arms Co., Inc.
Product Service
Legal Case #:7038

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		12/12/2011					

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Scott	Mitchell	94 County Rd 303	Greenwood	MS	38930		C 662-299-8915

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired on safety release	Cause:4079 Other - Unexamined Concern:1007 Fired on Safe Release		Unknown
C				

12/12/11 Per call from Mitchell, he just bought this rifle and the trigger pull was heavy when he first shot it so he adjusted it out (does not know what pull weight he adjusted it to) and it fired when he released the safety. He says it is a new rifle with a XMark Pro trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM	n/a			
Date Purchased	Where Purchased	Accessories	Original Owner			
			Y			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

12/12/11 Mailing ARS.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

ARS LABEL REQUEST FORM

DATE: 12/12/2011	Service Request # SR00006381
QUANTITY: 1	WEIGHT PER PACKAGE: 10 LBS
REQUESTED BY: mitchelcs	email address: Christy.Mitchell@remington.com

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	SCOTT MITCHELL 94 COUNTY RD 303 GREENWOOD, MS 38930 US SR00006381 Email: Christy
RETURN ITEM TO:	ILN Arms Services



4XX596 DEC 12, 2011 ACT WT 10.0 LBS #PK 1
 SVC GND COM BL WT 10.0 LBS
 TRACKING# 124XX5969067727227 ALL CURRENCY USD
 REF 1: SR00006381
 REF 2:

HANDLING CHARGE 0.00	FRT: 3RD
SHIPMENT PUB RATE CHARGES:	SVC T/P USD
DV 0.00	RS 0.50
DC 0.00	ROD 0.00
AH 0.00	PUB + HANDLING 9.61
TOT PUB CHG 9.61	

ATTN: Product Service #7038