Remington Arms Co., Inc. Product Service Legal Case #:7019

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 12/8/2011

12/7/2011 12/8/2011 248339

Customer Information

City Contact First Name **Last Name** Street Type Business State Zip Age

Fired on safety release

400 S Mickey Mantle Blvd Commerce OK 74339 Reporter Rhoades Gun Shop Rhoades Gun Sho W 918-875-4019

Incident Information

Claims Codes Repair Est. Medical Treatment **Medical Status** 

PI

PD Cause:4038 Could Not Duplicate Concern

Unknown Concern:1007 Fired on Safe Release

S

1/5/12 Per note with rifle, the owner had shot it a few times zeroing in the scope and it worked ok but when he was hunting and took it off safety adn without touching the trigger it went off. This happened 2 more times on an empty chamber. Also, the magazine has a problem as it only holds 2 rounds and should hold 3.cm

Firearm Information

Mfg. Type

Model/Ga.

**SKU** 

DOM

Remington

CONCERN:FSR

CF/BA

700/7MM REM MA

84082

G6735887 CC

4/1/2008 11:37:39 AM

Date Purchased

Where Purchased

Accessories

**Original Owner** U

GLENN ZANDERS FUR & SPORT

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Release of Claims

Release Date

Reimbursement

Cash Reim. Settlement Date APV Cash Date APV

Reset trigger pull to within specs, check over adn test fire at no charge

Settlement

Repair/Replacement Repair/Replacement

Cost

Date

1/5/2012

1/5/12 Per Ilion, could not duplicate concern. Trigger pull has been set below specs. Trigger has minimum return. Reset trigger pull to within specs, check over adn test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/8/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		26" 7MM REM MAG
Barrel	Date Code		CC
	Bore Plugged	False	9
	Bulged	False	
	Fired	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7019&Type=Case

1/5/2012

	Fired while Obstructed		<b>_</b>
	Muzzle/Crown Condition	Like new; Functioning	7
	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	<u> </u>
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	<u> </u>
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Like new; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	rests	False	
	Condition	Like new; Functioning	
Tricon	Pull	Select	2#
Trigger	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	X-Mark Pro	

Rhoades Gun Shop
400 S. Mickey Mantle Blvd.
Commerce, OK 74339
918-675-4019

Lhis rille-Rem M-

11-22-11

7019

26" CCY/08 Z#

1.	
	Dear Sir:
	This rifle Rem M-700 7mmMag
	SNG6735887 was bought
	SNG6735887 was bought from Zanders Spt Hools on 9-19-11
	and sold to one of my custoners
Section and design	he shot it a few times geroing
	he shot it a few times geroing in the scope, and it worked
-	OK but when he was
the spector of the	hunting and took of the Dafety fwithout touching the trigger
The second second	Safety fulithent touching the trigger
-	it went of!! This happene
-	2 more times on an empty
-	Chamber. Please repair + send
A	fack to me ASAP
-	also the magazine has
The state of	a problem, it is supposed to
of commence to	hold 3 rounds, but the 3rd
-	one will not feel from the
-	may it pops out & wont go
manifest of the last	in the Chamber. Please
Santon and the santon	repair Thank You Charles
2	Enclosed in my FFL

G6735887 Model: 700

RE00248339

could not dup heate concern.

TRIQ. pull has been set below

Specs. Triq has min return

Reset Triq. pull to within specs.

check over to ST Rim AT N/C

us roonly

	<u> </u>	C	<u>ر</u>	I	Gasta	T	
	D	EC	1	3	201	Q	

BY: ......







