

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
250232	12/13/2011	12/14/2011	12/14/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Scheels	---	Scheels	2101 W. 41st St.	Sioux Falls	SD	57105		W 605-334-7767 F 605-334-8936

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Concern:1008 Fired on Bolt Closing		Unknown	
C FBC				

Dealer sent gun in for consumer. The consumer stated they had a FBC. No damage or injury reported. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	84014	S6594374	BB	1/4/2007 8:40:51 PM

Date Purchased	Where Purchased	Accessories	Original Owner
	MT SPORTS, LLC	TWO PIECE BASE	U

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Replace TA @ n/c						

Repair/Replacement Cost	Repair/Replacement Date
\$46	1/11/2012

12/16/11: Per Ilion - Could not duplicate concern. To restore confidence in rifle, will replace TA, clean & test fire @ n/c. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/14/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 270 WIN SS FL

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7068&Type=Case>

1/11/2012

Barrel	Date Code		BB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS,SCRATCHES,FINISH WEAR
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	False		
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE



24"  
BDI/07  
5.5#  
.011

2101 W 41<sup>st</sup> St Sioux Falls, SD 57105  
Phone (605) 334-7767 Fax (605) 334-8936

December 7, 2011

Remington Arms Co  
14 Hoefler Ave  
Ilion, NY 13357

Manufacturer: Remington  
Model: 700  
Serial Number: S6594374  
Caliber/Gauge: 270  
SO#: 37088

Enclosed is a Remington 700. The owner states the gun fired when the bolt was closed without the trigger being engaged. Notify us of any charges to the owner before completing the work.

Sincerely,

*Eileen Fritz*

Eileen Fritz  
Gunsmith Office Manager

Enclosure

could not duplicate concern.  
To restore confidence in  
rifle, will replace TPA, clean &  
Test Rifle at N/C

Serial  
Number:

S6594374

Model: 700



RE00250232

RECEIVED  
DEC 18 2011

#260924

BY:.....













