

Remington Arms Co., Inc.
Product Service
Legal Case #:7922

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
281653	9/11/2012	9/12/2012	9/12/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	The Baron's Den		The Baron's Den	86321 College View Rd	Eugene	OR	97405		W 541-744-6229

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Fires when closing bolt	Concern:1008 Fired on Bolt Closing		Unknown
C				

9/21/12 Per letter with rifle, the gun fires when closing the bolt.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	85471	G6980433	PE	6/11/2010 10:29:25 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	HORTON DIST CO INC * LEW	SCOPE,RINGS,BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
To restore confidence in rifle, will replace TPA, check over, test at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	50.63	9/21/2012				

9/21/12 Per Ilion, could not duplicate concern. Magazine box misassm in stock before return. To restore confidence in rifle, will replace TPA, check over, test at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/12/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	THE STOCK HAS NOT HAD THE SAFETY CLEARANCE CUT OUT AND SAFE WAS DRAGGING IN THE STOCK.
Barrel	Description		20" 308 WIN FL HB
	Date Code		PE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SCOPE,RINGS,BASE

2011
PE61
3#

THE BARON'S DEN

7922


08/31/12

Remington Arms Co. Inc.
14 Hoefler Avenue
Ilion, NY 13356

Re: Remington 700 #G6980433

The enclosed rifle is being sent for repair. The gun fires when closing the bolt.

Yours truly,



Gayle Umenhofer
Enclosure: 2

RECEIVED
SEP 17 2012

BY:

Serial
Number:

G6980433

Model: 700



RE00281653

36321 College View Rd.
Eugene, OR
97405
541-744-6229

could not duplicate concern
mag. BOT misassm in stock before
return. To restore confidence in
rifle will replace TPA, check over
& test at N/C

unwarranty

27.-
23.63
50.63





