Remington Arms Co., Inc. Product Service Legal Case #:7816

\sim	T C	
000	Inform	OTION
Case	THOUSE	auvi.

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete 7/27/2012 8/23/2012 277626 8/6/2012 7/26/2012

Customer Information

Type **Business** First Name Last Name Street City State Zip Age Contact Reporter Jackson Hardware Shaun Gunter Jackson Hardwar 111 S. Main St. Brundidge AL36010 W 334-735-2773

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PD Shot hole in floor of truck

Cause: 4038 Could Not Duplicate Concern Gun discharged with no one Concern: 1006 Unexplained Discharge Safe OFF

Unknown

around

7/27/12: Shaun Gunter at Jackson Hardware called in. He stated a consumer brought the rifle to them today & said the gun was loaded & on Fire when it discharged & shot a hole in the floor of their truck. Consumer said no one was in the truck when this happened. No injury. df

Firearm Information

Mfg.

Type

Model/Ga. 700/308 WIN

SKU 84364

Bbl. Serial

DOM

Remington **Date Purchased**

CF/BA Where Purchased

Accessories

Original Owner

G7156434 AG 3/16/2012 10:42:26 AM

ELLETT BROTHERS, LLC

U

CONCERN:DISCHARGED IN HIS VEHICLE

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV APV

Replace TA @ n/c goodwill gesture

> Repair/Replacement Cost

Repair/Replacement Date

\$50

7/27/12: Mailing ARS & forms. df 8/23/12: Spoke w/Shaun at store. We agreed to replace TA, clean & test at no charge - goodwill gesture. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		8/21/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		22" 308 WIN VTR
	Date Code		AG
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7816&Type=Case

8/23/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning	j
	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Like new; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	<u> </u>
	Lift	Select	.010
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	16515	False	
	Condition	Like new; Functioning	
Trigger	Pull	Select	4.25#
riiggei	Altered	False	
	Sub-Assembly	X-Mark Pro	

4.23 /12 4.23 /12 4.23 /12

7816

July 27, 2012

Jackson Hardware Attn: Shaun Gunter 111 S. Main St. Brundidge, AL 36010

Phone: 334-735-2773

Ref: #7816, Model 700, Serial # G7156434

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our facility for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.


I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872





Service Request

Remington Service PO Box 700

Date of Request:

Date

07/27/2012

Printed: 07/27/2012

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number Serial Number / Description

SR00025360

G7156434

Model 700 RIFLE Caliber: 308

Customer:

JACKSON HARDWARE M/F: SHAUN GUNTER 111 S. MAIN ST.

BRUNDIDGE, AL 36010 US

Email:

Destination:

Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 7816

Parts And Service Details
Material Type

tails e Description

Qty Needed

Warranty

Price

rice Disc

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

. 00

Model Number: 700 VTK	Serial Number:	
Name: JACKSON HARDWARE	Date of Purchase:	
Address (no P		
111 SOUTH MAIN STREET		
City: BRUNDINGE	State: AL Zip: 34010	
Phone (Daytime): 334 735-2773	Fax: 334 735-2314	
E-mail Address: Shaun ລີ	TROYCABLE NET	
Please describe ye	our problem:	
The customer had the gun loaded with the safety OFF (He also has adjusted the trigger) and the gun discharged while it was in his rehield.		
500 charae	cters left	
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.		
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.		
Print	Reset	

ARS LABEL REQUEST FORM

DATE:	07/27/2012	Service Request #	SR00025360
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
	:		
	:		
:			
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com	

LABEL INFORMATION

MAIL LABEL TO:	JACKSON HARDWARE M/F: SHAUN GUNTER 111 S. MAIN ST.· SR00025360 BRUNDIDGE, AL 36010 US Email:
RETURN ITEM TO:	ILN
	Arms Services

4XX596 JUL 27, 2012 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969065942533 ALL CURRENCY USD REF 1:SR00025360 REF 2:

HC 0.00 CNS 0.00 FRT: 3RD SHIPMENT PUB RATE CHARGES: SVC T/P USD DV 0.00 DC 0.00 COD 0.00 AS 0.50 DGD 0.00 AH 0.00 0.00 ROD 0.00 TOT PUB CHG 10.31 PUB+HANDLING 10.31

ATTN: Product Service



