

Remington Arms Co., Inc.
Product Service
Legal Case #:7448

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
260200	2/28/2012	2/29/2012	2/29/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Pctcr	Murphy	2394 East Sheldon Rd	Enosburg Falls	VT	05450		E pcmurphy2010@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

SR# 12683 - Gun fired while working bolt. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	84218	G6639586	BB	1/24/2007 9:31:26 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	HENRYS TACKLE LLC		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Replace TA @ n/c - goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$46					

3/2/12: Per Ilion - Could not duplicate concern. As a goodwill gesture, to restore confidence in rifle, will replace TA, check over & test fire @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/29/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 308 WIN HB
	Date Code		BB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	SCRATCHED,MARRED
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.004
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



copy

Parts and Repairs: P:800-243-9700; F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

26"
BB1/07
3#
1004

Service Request Number SR00012683	Serial Number / Description G6639586 Model 700 RIFLE Caliber: 308	Date of Request: 02/14/2012 Date Printed: 02/14/2012
Customer: PETER MURPHY 2394 EAST SHELDON RD ENOSBURG FALLS, VT 05450 US Email: pcmurphy2010@yahoo.com	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US Email:	

7448

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason for Return

M240 - BOLT LOCK SAFETY MODIFICATION
M295 - EVALUATE AND REPAIR

Service Request Section

GUN FIRED WHILE WORKING BOLT


Parts and Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

G6639586
Model: 700



RE00260200



BY:

could not disp. concern. As a
Good Will Gesture to restore
confidence in rifle will replace
TAA, check over & test at N/C

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

~~260974~~
260974
Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00

Bill of Sale

I, Sam Vaillancourt, Sell my

Remington model 700, .308

Serial number G6639586

to Peter Murphy For the

amount of \$ 1.00 on

January 10th, 2012


Sam Vaillancourt

1/10/12


Peter Murphy



