

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7913

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 280643 | 9/6/2012    | 9/7/2012        | 9/7/2012    |               |         |     |          |

## Customer Information

| Type     | Business                | First Name      | Last Name | Street            | City   | State | Zip   | Age | Contact                     |
|----------|-------------------------|-----------------|-----------|-------------------|--------|-------|-------|-----|-----------------------------|
| Reporter | Tooele City Police Dept | Tooele City Pol |           | 323 North Main St | Tooele | UT    | 84074 |     | E lcollings@tooelecitey.org |

## Incident Information

| Claims | Codes                             | Repair Est.                        | Medical Treatment | Medical Status |
|--------|-----------------------------------|------------------------------------|-------------------|----------------|
| PI     |                                   |                                    |                   |                |
| PD     | Cause:4038                        | Could Not Duplicate Concern        |                   | Unknown        |
| S      | Discharged after chambering round | Concern:1008 Fired on Bolt Closing |                   |                |
| C      |                                   |                                    |                   |                |

9/21/12 Per note on SR, feeding issue with 2nd round. Accidental discharge after chambering round. Gripped rifle after chambering when rifle discharged. No injury or property damage.cm

## Firearm Information

| Mfg.           | Type                      | Model/Ga.   | SKU            | Serial   | Bbl. | DOM                  |
|----------------|---------------------------|-------------|----------------|----------|------|----------------------|
| Remington      | CF/BA                     | 700/308 WIN | 84207          | G6871905 | PD   | 6/10/2009 8:54:41 AM |
| Date Purchased | Where Purchased           | Accessories | Original Owner |          |      |                      |
|                | ACUSPORT (OH) CORPORATION | SCOPE BASE  | U              |          |      |                      |

CONCERN: GRIPPED RIFLE AFTER CHAMBERING WHEN RIFLE DISCHARGED

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

| Settlement                                                                              | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-----------------------------------------------------------------------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| To restore confidence in rifle, will replace TPA, check over and test fire at no charge |                         |                         |               |                 |                |               |
|                                                                                         | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                                                                                         | 50.39                   | 9/21/2012               |               |                 |                |               |

9/21/12 Per Ilion, could not duplicate concern. To restore confidence in rifle, will replace TPA, check over and test fire at no charge.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                        | Comment                                                                                                                                           |
|-------------|--------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|
| Examination | Examiner     |                             | B.TRAVIS                                                                                                                                          |
|             | Exam Date    |                             | 9/7/2012                                                                                                                                          |
|             | Product Type |                             | RF                                                                                                                                                |
|             | Action Type  |                             | A                                                                                                                                                 |
|             | Assigned To  |                             | T.NAGLE                                                                                                                                           |
| Cause       | 4038         | Could Not Duplicate Concern | APPEARS TRIG PULL SCREW WAS SET TO FAR OUT DURING FACTORY SETTING,SO WHEN THE TRIG ADJUSTING SCREW IS TURNED OUT THERE WILL BE A MIN TRIG RETURN. |
|             | Description  |                             | 20" 308 WIN                                                                                                                                       |
|             | Date Code    |                             | PD                                                                                                                                                |
|             | Bore Plugged | False                       |                                                                                                                                                   |
|             | Bulged       | False                       |                                                                                                                                                   |

|                          |                        |                            |            |
|--------------------------|------------------------|----------------------------|------------|
| Barrel                   | Fired                  | False                      |            |
|                          | Fired while Obstructed |                            |            |
|                          | Muzzle/Crown Condition | Slightly Worn; Functioning |            |
| Bolt                     | Firing Pin             | Slightly Worn; Functioning |            |
|                          | Shroud                 | Slightly Worn; Functioning |            |
|                          | Face                   | Slightly Worn; Functioning |            |
|                          | Handle                 | Slightly Worn; Functioning |            |
|                          | Stop                   | Slightly Worn; Functioning |            |
| Extractor                | Condition              | Slightly Worn; Functioning |            |
|                          | Cut Condition          | Slightly Worn; Functioning |            |
|                          | Ext/Eject Test         | False                      |            |
| Locking                  | Block Condition        | ---Select---               |            |
|                          | Lug Condition          | Slightly Worn; Functioning |            |
|                          | Notch Condition        | ---Select---               |            |
| Overall                  | Exterior Condition     | Slightly Worn; Functioning |            |
|                          | Stock Condition        | Slightly Worn; Functioning |            |
|                          | Fore End Condition     | ---Select---               |            |
| Receiver                 | Condition              | Slightly Worn; Functioning |            |
|                          | Bulged                 | False                      |            |
| Safety                   | Description            |                            | XMP SAFETY |
|                          | Function               | Like new; Functioning      |            |
|                          | Sub-Assembly           | Non-ISS                    |            |
| Sear                     | Lift                   | ---Select---               | .011       |
|                          | Notch                  | Slightly Worn; Functioning |            |
|                          | Tests                  | Test Fired                 | False      |
| Feeding Test             |                        | False                      |            |
| Trigger                  | Condition              | Slightly Worn; Functioning |            |
|                          | Pull                   | ---Select---               | 4#         |
|                          | Altered                | False                      |            |
|                          | Sub-Assembly           | X-Mark Pro                 |            |
| Non-Remington Components | Description            |                            | SCOPE BASE |

Madison, NC 27025-0700

Parts and Repairs: P-800-243-9700 F-336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

2011  
PDG/c  
47#  
.011

Service Request Number: SR00027280  
Serial Number / Description: G6871905  
Model 700 RIFLE Caliber: 308

7913

Date of Request: 08/23/2012  
Date Printed: 08/23/2012

Customer:  
TOOELE CITY POLICE DEPARTMENT  
323 NORTH MAIN ST  
TOOELE, UT 84074 US

Destination:  
Arms Services  
14 Hoeller Ave  
Hilicon, NY 13357 US

Email: kcollings@tooelecipolice.org

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

CD

Reason For Return  
M138 - WILL NOT FEED PROPERLY  
M992 - ACCD FIRE

Service Request Section  
Feeding issue with 2nd and 3rd round. Accidental discharge after chambering round. Gripped rifle a  
fter chambering when rifle discharged. No injury or prop. damage.

| Material | Type | Description | Qty Needed | Warranty | Price | Disc | Amount |
|----------|------|-------------|------------|----------|-------|------|--------|
|----------|------|-------------|------------|----------|-------|------|--------|

Serial Number:

G6871905

Model: 700



RE00280643

RECEIVED  
SEP 17 2012

BY: .....

could not duplicate concern.  
To restore confidence in rifle  
will replace TPA, check over +  
test fire at N/C

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

\$260974

|                |        |
|----------------|--------|
| Sub Total:     | .00    |
| Est Sales Tax: | .00    |
| Grand Total:   | \$ .00 |



14 West Vine Street  
Tooele, Utah 84074  
435-882-7472

Name: Tooele City Police Dep Date: 09-24-09

Address: \_\_\_\_\_

Phone #: \_\_\_\_\_

ID#: \_\_\_\_\_ Exp: \_\_\_\_\_ DOB: \_\_\_\_\_

Height: \_\_\_\_\_ Weight: \_\_\_\_\_ Eyes: \_\_\_\_\_ Hair: \_\_\_\_\_ Race: \_\_\_\_\_ Male / Female

Lay-A-Way Due in 90 Days ☐ NO REFUNDS OR EXCHANGES

| Quan.  | Description                                                                                 | Amount   |
|--------|---------------------------------------------------------------------------------------------|----------|
| V33894 | Enfield #4MK1 #V17885<br>303 rifle                                                          |          |
| V33895 | H&R #255102 12ga<br>Shotgun                                                                 |          |
| V33896 | Remington 552 22 LR<br>Rifle No Serial No.                                                  |          |
| V33897 | Remington 700 30-06<br>Rifle #6552624<br>CVA 50 cal. Black Powder<br>rifle #61-13-027233-09 |          |
|        | paid out                                                                                    | \$650.00 |

ALL claims and returned goods MUST be accompanied by this receipt

Received by: DEM





